

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23002322/RPA3Q2**Date:** 07/07/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

SP2003907937

Claimant Vehicle No : SKQ7L**Insured Vehicle No :**

SNH8059X

Date of Loss: 23/02/2023

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKQ7L**

Make & Model: MERCEDES-BENZ AMG GT 63 S, 4.0 4MATIC+ (R20 LED) (A)

Engine No: 17798060142525

Reg. Date: 04/08/2020 (Man. Year: 2020)

Chassis No: W1K2906892A032405

Colour: Black

Odometer: 21431 km

Engine Capacity: 3982 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/40Z R20

Rear Tyre Size:

265/40Z R20

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,031.69	11,301.96	729.73	6.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	2,360.00	1,120.00	32.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,511.69	13,661.96	1,849.73	11.92
+ GST 8.00/8.00% (S\$)	1,240.94	1,092.96	147.98	11.92
Nett Amount (S\$)	16,752.63	14,754.92	1,997.71	11.92
+ Loss of Use (4.0 x S\$120.00/day) (S\$)		480.00		
Nett Liability (S\$)		15,234.92		

INSPECTION

Date of Assignment: 02/03/2023

Date Inspected: 10/03/2023 Inspected At:

Cycle & Carriage Industries Pte Ltd (Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jul 2023)
Parts:	M1-COUPE	MERCEDES-BENZ AMG GT 63 S 4.0 4MATIC+ (R20 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKQ7L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT AMG BUMPER	Scratched	2,918.36 FS	*2,918.36 FS
2	1		*LH/FRONT BUMPER LOWER TRIM STRIP	Necessary	134.01 FS	*134.01 FS
3	1		*RH/FRONT BUMPER LOWER TRIM STRIP	Necessary	134.01 FS	*134.01 FS
4	1		*CTR/FRONT BUMPER LOWER TRIM STRIP	Necessary	194.01 FS	*194.01 FS
5	1		*TOWING EYE COVER	Not Necessary	86.17 FS	*- FS
6	1		*LH/UPPER FRONT BUMPER BRACKET	Cracked	184.09 FS	*184.09 FS
7	1		*RH/UPPER FRONT BUMPER BRACKET	Cracked	184.71 FS	*184.71 FS
8	1		*FRONT BUMPER TOP BASIC CARRIER	Cracked	278.33 FS	*278.33 FS
9	1		*FRONT BUMPER TOP INNER BASIC CARRIER	Not Necessary	169.64 FS	*- FS
10	8		*SPRING NUT	Not Necessary	28.16 FS	*- FS
11	1		*MOUNTING CONSOLE	Not Necessary	345.55 FS	*- FS
12	1		*RH/HEADLAMP BOTTOM BRACKET	Not Necessary	100.21 FS	*- FS
13	1		*RH /HEADLAMP UNIT	Scratched	7,167.64 FS	*7,167.64 FS
14	20		*RIVET FOR BUMPER	Necessary	106.80 FS	*106.80 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	12,031.69 11,301.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,920.00	960.00
2	RESPRAY FRONT BUMPER	New	960.00	800.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	480.00	480.00
4	TO REMOVE,REPLACE HEADLAMP WITH FOCUS	New	120.00	120.00
Gross Labour Cost (\$\$)			3,480.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >