

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23002328/AYA3Q2**Date:** 26/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070055721
Claimant Vehicle No :	SNG944Z	Insured Vehicle No :	SMT804M
Date of Loss:	03/03/2023	Nature of Claim:	TP
		Claim No:	4679206282SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG944Z	Engine No:	2ZR2N18337
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800511192
Reg. Date:	07/07/2022 (Man. Year: 2021)	Odometer:	79889 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Teraflex 6 mm	Rear Left Side:	Teraflex 6 mm
Front Right Side:	Teraflex 6 mm	Rear Right Side:	Teraflex 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,036.40	3,962.47	2,073.93	34.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	1,970.00	1,760.00	47.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,766.40	5,932.47	3,833.93	39.26
Approved Total (Overridden) (S\$)		4,700.00		
(S\$)	9,766.40	4,700.00	5,066.40	51.88
+ GST 8.00/8.00% (S\$)	781.31	376.00	405.31	51.88
Nett Amount (S\$)	10,547.71	5,076.00	5,471.71	51.88
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		26.75		
Nett Liability (S\$)		5,802.75		

INSPECTION

Date of Assignment:	06/03/2023	MG Solution Pte Ltd (HQ)
Date Inspected:	06/03/2023 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*TAILGATE	Dented	2,080.50 FL	*1,817.00 FL	
2	1		*TAILGATE LOGO	Not Necessary	85.00 FL	*- FL	
3	1		*TAILGATE EMBLEM HYBRID SYNERGY DRIVE	Necessary	82.50 FL	*82.50 FL	
4	2		*TAILGATE HINGE	Not Necessary	260.00 FL	*- FL	
5	2		*TAILGATE DAMPER	Not Necessary	460.00 FL	*- FL	
6	1		*TAILGATE LOCK	Damaged	480.00 FL	*395.00 FL	
7	1		*TAILGATE LOCK CATCH	Not Necessary	90.00 FL	*- FL	
8	1		*TAILGATE INNER BOARD TRIM	Cracked	766.20 FL	*589.00 FL	
9	1		*TAILGATE WEATHERSTRIP	Not Necessary	330.00 FL	*- FL	
10	1		*TAILGATE INNER HANDLE	Not Necessary	90.00 FL	*- FL	
11	1		*REAR WINDSCREEN MOULDING	Necessary	190.00 FL	*190.00 FL	
12	1		*TAILGATE ALTERNATIVE	Cracked	210.00 FL	*156.00 FL	
13	1		*TAILGATE BUZZEL	Cracked	150.30 FL	*85.00 FL	
14	1		*REAR BUMPER	Deformed	822.30 FL	*822.30 FL	
15	2		*REAR BUMPER SIDE RETAINER	Not Necessary	124.80 FL	*- FL	
16	1		*REAR BUMPER TOWING COVER	Not Necessary	98.20 FL	*- FL	
17	1		*REAR END PANEL	Dented	666.50 FL	*666.50 FL	
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	288.90 FL	*- FL	
19	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS	
20	1		*SET TAILGATE INNER BOARD CLIPS	Necessary	20.00 FS	*20.00 FS	
21	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS	
22	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS	
23	1		*SET REAR END PANEL GARNISH CLIP	Not Necessary	20.00 FS	*- FS	
24	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*60.00 FS	
25	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (S\$)	7,855.20	5,163.30
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,818.80	1,200.83
					Total Parts (S\$)	6,036.40	3,962.47

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	120.00	30.00
5	TO CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
6	TO TRANSFER TAIL GATE MECHANISM	New	180.00	60.00
7	LABOUR TO REMOVE AND REFIT WINDSCREEN	New	120.00	120.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
Gross Labour Cost (\$\$)			3,730.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >