



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNB 7845G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	SEALANT (NETT)-LH FRT DOOR (SN)	NECESSARY	80.00	80.00
1	COVER, FR BUMPER (SN)	TO REPAIR SEE LABOUR	751.30	-
1	SEAL, HOOD TO FR END (SN)	NOT NECESSARY	112.40	-
1	RETAINER, FR BUMPER (SN)	BROKEN	120.70	120.70
1	BRACKET, FR BUMPER, (SN)	NOT NECESSARY	192.70	-
8	CLIP @\$3.00 (SN)	NECESSARY	24.00	24.00
1	GUARD, FR BUMPER (SN)	CUT	706.80	706.80
1	FENDER SUB-ASSY, FR (SN)	BUCKLED	1,510.80	1,510.80
1	LINER, FR FENDER, LH (SN)	CUT	296.00	296.00
10	CLIP @\$3.00 (SN)	NECESSARY	30.00	30.00
1	SEAL, FR FENDER, LH (SN)	NOT NECESSARY	34.20	-
1	PROTECTOR, FR FENDER (SN)	CRUSHED	110.20	110.20
1	UNIT, HEADLAMP (SN)	NOT NECESSARY	7,847.70	-
1	PANEL SUB-ASSY, FR (SN)	BUCKLED	2,115.70	2,115.70
1	TAPE, BLACK OUT, (SN)	NECESSARY	13.20	13.20
1	STRIPE, FR DOOR, (SN)	NECESSARY	52.30	52.30
1	STRIPE, FR DOOR (SN)	NECESSARY	31.40	31.40
1	WEATHERSTRIP, FR (SN)	NOT NECESSARY	259.30	-
1	CHECK ASSY, FR DOOR (SN)	BENT	265.50	265.50
1	HINGE ASSY, FR DOOR, (SN)	BENT	117.20	117.20
1	HINGE ASSY, FR DOOR, (SN)	BENT	133.20	133.20
1	LOCK ASSY, FR DOOR (SN)	NOT NECESSARY	675.00	-
1	PANEL SUB-ASSY, RR (SN)	NOT NECESSARY	1,974.20	-
1	MUDGUARD SUB-ASSY, (SN)	CUT	59.60	59.60
1	MOULDING SUB-ASSY, (SN)	SCRATCHED	415.80	415.80
1	MOULDING SUB-ASSY, (SN)	NOT NECESSARY	287.60	-
1	MOULDING ASSY, BODY (SN)	NOT NECESSARY	578.00	-
1	WHEEL, DISC (SN)	CUT	2,782.20	2,782.20
1	ABSORBER ASSY (SN)	NOT NECESSARY	567.80	-

Report Ref No. CS/FCI23002339/Sqy3m4



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ARM SUB-ASSY, (SN)	NOT NECESSARY	954.20	-
1	JOINT ASSY, LWR BALL (SN)	NOT NECESSARY	286.30	-
1	KNUCKLE, STEERING, (SN)	NOT NECESSARY	883.30	-
1	HUB & BEARING ASSY, (SN)	NOT NECESSARY	733.70	-
1	MEMBER ASSY, SIDE, (SN)	NOT NECESSARY	458.10	-
1	BRIDGE ALENZA 001 225/60R18 (SN) (ADDITIONAL)	TORN	351.00	351.00
1	MIRROR ASSY, OUTER (SN) (ADDITIONAL)	CUT	2,170.50	2,170.50
			28,011.90	11,416.10
	<b>LABOUR</b>			
	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION.		366.36	366.36
	CHECK LIGHTING & WIRING SYSTEM.		198.00	198.00
	TO CONDUCT ADJUSTMENT ON FRT WAVE RADAR SENSOR.		198.00	198.00
	REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING.		99.00	99.00
	CONDUCT FULL WHEEL ALIGNMENT.		198.00	198.00
	REPLACE FRT LH SUSPENSION SYSTEM.	NOT NECESSARY	792.00	-
	TRANSFER & INSTALL COMPONENTS TO NEW DOOR.		396.00	396.00
	TO RESET ECU AND REPROGRAMME.		198.00	198.00
	REPLACE LH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN LH ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF COVER, FR BUMPER.		3,960.00	2,376.00
	RESPRAY JOB ON LH ACCIDENT AFFECTED AREAS.		3,936.00	2,624.00
			10,341.36	6,653.36
<b>GRAND TOTAL</b>			<b>38,353.26</b>	<b>18,069.46</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>18,069.46</b>

Report Ref No. CS/FCI23002339/Sqy3m4

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.