



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23002339/Sqy3m4 Date: 26/06/2023  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	YP 9385A	Veh. Inspected	SNB 7845G
Policy No.	D22099240	Coverage (\$)	0.00
Claim No.	D23000776MFCV	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	06/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA HARRIER	c.c	1987
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JTEAC3BH90J000214	Colour	WHITE
Odometer	13736 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/60R18	BRIDGESTONE	5 mm
L/H Front Tyre	225/60R18	BRIDGESTONE	5 mm
R/H Rear Tyre	225/60R18	BRIDGESTONE	5 mm
L/H Rear Tyre	225/60R18	BRIDGESTONE	5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	03/03/2023	Inspection Date	06/03/2023
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	