

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD	F	Ref:	CS3/LPC23002343/Tny3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	С	Date:	16/03/2023	
			C	Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SFU 49D	Veh. Inspected		SCP 32M	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	23/23/23/VP05/027065	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		06/03/2023	
2.	. Vehicle Particulars & Condition					
	Make & Model	TOYOTA LEXUS ES250	c.c		2494	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JTHBJ1GG702090801	Colour		GREY	
	Odometer	139612 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	255/35 R19	BRIDGESTONE		6 mm	
	L/H Front Tyre	255/35 R19	BRIDGESTONE		6 mm	
	R/H Rear Tyre	255/35 R19	BRIDGESTONE		6 mm	
	L/H Rear Tyre	255/35 R19	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS UNDERCARRIAGE	STAINED DAMAGES AT THE FRONT O/S PORTION AND				
5.		General Information				
	Accident Date	03/03/2023	Inspect Date / Ti	ime	06/03/2023 ( 04:25 PM )	
	Survey held at	INFINITY CAPITAL & INSURANCE				
		38 WOODLAND CLOSE #01-08 MEGA @ WOODLAND SINGAPORE 737856				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC23002343/Tny3e2

Inspected By

MOHAMAD TAUFIKH M.MATAI, AMSAE-A K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**