

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 7478Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER BEAM BRACKET LH	TO REPAIR SEE LABOUR	143.10	-
1	TAIL GATE HINGE	TO REPAIR SEE LABOUR	53.90	-
2	TAIL LAMP L/R @\$312.00	CRACKED	624.00	511.20
1	TAIL LAMP HOLDER LH	TO REPAIR SEE LABOUR	99.50	-
1	LICENSE PLATE HOLDER	TO REPAIR SEE LABOUR	55.20	-
	LESS 25% DISCOUNT		-243.93	-127.80
			731.77	383.40
1	REAR BUMPER BEAM (SN)	BENT	1,084.80	600.00
	LESS 25% DISCOUNT		-271.20	-
			813.60	600.00
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	SERVICEABLE	250.00	-
1	REAR LICENSE PLATE (SN)	BENT	40.00	20.00
			290.00	20.00
	<u>LABOUR</u>			
	TO REMOVE & REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTINGS.		80.00	20.00
	TO REMOVE ,REPAIR & REPLACE DAMAGED BODYPARTS ,REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM BRACKET LH ,TAIL GATE HINGE ,TAIL LAMP HOLDER LH AND LICENSE PLATE HOLDER .		500.00	300.00
	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS.		400.00	200.00
	TO REMOVE & RENEW REVERSE SENSOR .	NOT NECESSARY	100.00	-

Report Ref No. CS/AGI23002345/Kvy3q2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

1,523.40

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	RUST PROOFING ON AFFECTED PORTIONS.	NOT NECESSARY	80.00	-
			1,160.00	520.00
	GRAND TOTAL		2,995.37	1,523.40

Report Ref No. CS/AGI23002345/Kvy3q2

KONG SENG CHEONG

Licensed Appraiser