



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23002345/Kvy3q2 Date: 15/05/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJW 7585T	Veh. Inspected	YQ 7478Z	
Policy No.	P10357102R02	Coverage (\$)	0.00	
Claim No.	C10020846 /CD	Excess (\$)	0.00	
Assign From	MAYBIE CHUA	Assign Date	06/03/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA DYNA (M)	c.c	2755	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	JHHAGV46X0K002447	Colour	WHITE	
Odometer	24884 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BRIDGESTONE	8 mm	
L/H Front Tyre	195 R15X8	BRIDGESTONE	8 mm	
R/H Rear Tyre	145/80 R13 (D)	BRIDGESTONE	7/7 mm	
L/H Rear Tyre	145/80 R13 (D)	BRIDGESTONE	7/7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	03/03/2023	Inspection Date	21/03/2023	
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	