

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002347/SVP3Q2**Date:** 27/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00007212200		
Claimant Vehicle No :	GBD7680X	Insured Vehicle No :	CB6617K		
Date of Loss:	03/03/2023	Nature of Claim:	TP	Claim No:	SNM23D201632/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD7680X	Engine No:	ZD30347728K
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Chassis No:	JN1SC2F24Z0857076
Reg. Date:	28/04/2015 (Man. Year: 2014)	Odometer:	163523 km
Colour:	Silver		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,318.68	4,168.12	10,150.56	70.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,380.00	2,150.00	60.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,848.68	5,548.12	12,300.56	68.92
Approved Total (Overridden) (S\$)		4,450.00		
(S\$)	17,848.68	4,450.00	13,398.68	75.07
+ GST 8.00/8.00% (S\$)	1,427.89	356.00	1,071.89	75.07
Nett Amount (S\$)	19,276.57	4,806.00	14,470.57	75.07

INSPECTION

Date of Assignment:	03/03/2023	
Date Inspected:	06/03/2023	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Jul 2023)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD7680X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,988.40 FL	*1,399.00 FL
2	1		*TAILGATE NISSAN STICKER	Necessary	189.00 FL	*175.00 FL
3	1		*TAILGATE RH SIDE HINGE	Not Necessary	76.40 FL	*- FL
4	1		*TAILGATE RH SIDE HINGE PIN	Not Necessary	18.00 FL	*- FL
5	1		*TAILGATE CENTRE HINGE	Not Necessary	76.40 FL	*- FL
6	1		*TAILGATE CENTRE HINGE PIN	Not Necessary	18.00 FL	*- FL
7	1		*TAILGATE LH SIDE HINGE	Not Necessary	76.40 FL	*- FL
8	1		*TAILGATE LH SIDE HINGE PIN	Not Necessary	18.00 FL	*- FL
9	1		*TAILGATE RH LOCK CATCH LOCK	Not Necessary	291.90 FL	*- FL
10	1		*TAILGATE LH LOCK CATCH LOCK	Not Necessary	291.90 FL	*- FL
11	1		*TAILGATE LOWER PANEL	Not Necessary	886.40 FL	*- FL
12	1		*TAILGATE RH LOWER SIDE PANEL	Not Necessary	258.70 FL	*- FL
13	1		*TAILGATE RH LOWER SIDE PANEL RUBBER SENSOR	Not Necessary	35.50 FL	*- FL
14	1		*TAILGATE LH LOWER SIDE PANEL	Not Necessary	258.70 FL	*- FL
15	1		*TAILGATE LH LOWER SIDE PANEL RUBBER STOPPER	Not Necessary	35.50 FL	*- FL
16	1		*REAR NUMBER PLATE HOLDER	Not Necessary	95.80 FL	*- FL
17	1		*REAR NUMBER PLATE LAMP	Not Necessary	78.40 FL	*- FL
18	1		*RH SIDE GATE	Not Necessary	2,311.40 FL	*- FL
19	1		*RH SIDE GATE RUBBER STOPPER	Not Necessary	35.50 FL	*- FL
20	1		*LH SIDE GATE	Dented	2,311.40 FL	*1,699.00 FL
21	1		*LH SIDE GATE RUBBER STOPPER	Not Necessary	35.50 FL	*- FL
22	1		*RH TAILLAMP ASSY	Cracked	256.90 FL	*256.90 FL
23	1		*RH TAILLAMP BRACKET	Not Necessary	189.70 FL	*- FL
24	1		*LH TAILLAMP ASSY	Cracked	256.90 FL	*256.90 FL
25	1		*LH TAILLAMP BRACKET	Not Necessary	189.70 FL	*- FL
26	1		*REAR SPARE TYRE CARRIAGE	Not Necessary	244.80 FL	*- FL
27	1		*TAILGATE 70KM/H STICKER	Necessary	28.00 FS	*20.00 FS
28	1		*TAILGATE 6 PAX STICKER	Necessary	28.00 FS	*20.00 FS
29	1		*TAILGATE INNER CHECKER PANEL	Dented	850.00 FS	*500.00 FS
30	1		*SET TAILGATE INNER CHECKER PANEL RIVETS	Necessary	80.00 FS	*20.00 FS
31	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
32	1		*SET REAR REVERSE SENSOR	Faulty	350.00 FS	*200.00 FS
33	1		*TAILGATE LOWER PANEL JOINT SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*FLOOR DECK CHECKER PANEL	Not Necessary	1,200.00 FS	*- FS
35	1		*SET FLOOR DECK CHECKER PANEL RIVETS	Not Necessary	100.00 FS	*- FS
36	1		*LH SIDE GATE CHECKER PANEL	Not Necessary	950.00 FS	*- FS
37	1		*SET LH SIDE GATE CHECKER PANEL RIVETS	Not Necessary	80.00 FS	*- FS
38	1		*RH SIDE GATE CHECKER PANEL	Not Necessary	950.00 FS	*- FS
39	1		*SET RH SIDE GATE CHECKER PANEL RIVETS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,371.20	4,546.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,052.52	378.68
Total Parts (\$\$)	14,318.68	4,168.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT /WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,400.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,400.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	70.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	40.00
5	REMOVE AND REPLACE REAR REVERSE SENSORS TO ASSIST REPAIR	New	100.00	30.00
6	REMOVE AND REPLACE CHECKER PANEL AND RIVETS TO ASSIST REPAIR	New	480.00	80.00
Gross Labour Cost (S\$)			3,530.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >