

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23002358/TVP3E2**Date:** 31/05/2023**REFERENCE**

Insured/Claimant:	YEO KAI KIAT KELLY	Policy No:	7220039816	
Date of Loss:	01/03/2023	Nature of Claim:	OD	Claim No: 9453206333SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA1979K		
Make & Model:	AUDI A3, 1.5 SEDAN TFSI S TRONIC (18") (A)	Engine No:	DFY302010
Reg. Date:	30/11/2021 (Man. Year: 2021)	Chassis No:	WAUZZZGY4NA013698
Colour:	Black	Odometer:	20473 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$146,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,107.20	13,087.12	27,020.08	67.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,734.00	10,334.00	10,400.00	50.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	60,841.20	23,421.12	37,420.08	61.50
+ GST 8.00/8.00% (S\$)	4,867.30	1,873.69	2,993.61	61.50
Nett Amount (S\$)	65,708.50	25,294.81	40,413.69	61.50

INSPECTION

Date of Assignment:	06/03/2023		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	03/03/2023	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	15.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,778.00 FS	*1,422.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	307.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - RH	Deformed	137.00 FS	*109.60 FS
4	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	458.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Deformed	281.00 FS	*224.40 FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Deformed	71.00 FS	*56.16 FS
7	1		*FRONT BUMPER SPOILER	Deformed	345.00 FS	*275.60 FS
8	1		*FRONT BUMPER TRIM COVER - RH	Cut	110.00 FS	*87.60 FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	181.00 FS	*144.40 FS
10	1		*FRONT PARKING AID SENSOR SUPPORT - RH	Not Necessary	46.00 FS	*- FS
11	1		*RADIATOR GRILLE	Not Necessary	1,167.00 FS	*- FS
12	1		*RADIATOR GRILLE CLOSING ELEMENT - CENTER	Not Necessary	223.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	793.00 FS	*- FS
14	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	127.00 FS	*- FS
15	1		*FRONT BUMPER GUIDE SECTION - RH	Deformed	57.00 FS	*45.60 FS
16	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	22.00 FS	*- FS
17	1		*FRONT BUMPER TOP COVER	Not Necessary	94.00 FS	*- FS
18	1		*CAUTION SIGN STICKER	Not Necessary	17.00 FS	*- FS
19	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
20	1		*HORN HIGH TONE - RH	Not Necessary	165.00 FS	*- FS
21	2		*HORN BRACKET	Not Necessary	54.00 FS	*- FS
22	2		*HORN BRACKET - RH	Not Necessary	75.00 FS	*- FS
23	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	286.00 FS	*- FS
24	1		*FRONT PARKING AID SENSOR - RH	Not Necessary	294.00 FS	*- FS
25	4		*FRONT PARKING AID SEAL RING	Not Necessary	54.00 FS	*- FS
26	1		*SET FRONT BUMPER WIRING	Not Necessary	254.00 FS	*- FS
27	1		*FRONT FENDER - RH	Bent	1,313.00 FS	*1,050.40 FS
28	1		*FRONT FENDER RIVET (3PCS)	Necessary	16.00 FS	*16.00 FS
29	1		*FRONT FENDER CLOSING ELEMENT - RH	Deformed	34.00 FS	*26.88 FS
30	1		*FRONT FENDER BRACKET - RH	Bent	49.00 FS	*38.72 FS
31	1		*FRONT FENDER BRACKET - RH	Bent	38.00 FS	*29.76 FS
32	1		*FRONT FENDER BRACKET - RH	Bent	34.00 FS	*26.88 FS
33	1		*FRONT FENDER BRACE - RH	Bent	104.00 FS	*82.80 FS
34	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	127.00 FS	*- FS
35	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	39.00 FS	*- FS
36	1		*FRONT FENDER INSULATION - RH	Not Necessary	51.00 FS	*- FS
37	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	198.00 FS	*158.00 FS
38	1		*FRONT WHEEL HOUSING LINE CLOSING ELEMENT - RH	Not Necessary	24.00 FS	*- FS
39	1		*BONNET	Repair	3,330.00 FS	*- FS
40	1		*BONNET ATTACHMENT PARTS	Not Necessary	269.00 FS	*- FS
41	1		*BONNET IMPACT PROTECTION	Not Necessary	32.00 FS	*- FS
42	1		*BONNET ENGINE SOUND ABSORBER	Not Necessary	223.00 FS	*- FS
43	1		*BONNET STRIKER - RH	Not Necessary	130.00 FS	*- FS
44	1		*BONNET LOCK - RH	Not Necessary	241.00 FS	*- FS
45	1		*BONNET RELEASE ELEMENT	Not Necessary	69.00 FS	*- FS
46	1		*BONNET RELEASE LEVER	Not Necessary	16.00 FS	*- FS
47	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	66.00 FS	*- FS
48	1		*BONNET RELEASE CABLE COVER	Not Necessary	12.00 FS	*- FS
49	1		*FRONT PLENUM CHAMBER COVER	Not Necessary	187.00 FS	*- FS
50	1		*HEADLIGHT - RH	Cracked	4,323.00 FS	*3,458.40 FS
51	1		*HEADLIGHT HOSE - RH	Not Necessary	29.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*LIFT CYLINDER - RH	Not Necessary	223.00 FS	*- FS
53	1		*LIFT CYLINDER HOSE	Not Necessary	112.00 FS	*- FS
54	1		*LOCK CARRIER	Not Necessary	1,030.00 FS	*- FS
55	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	22.00 FS	*- FS
56	6		*READY-MIX COOLANT	Not Necessary	326.00 FS	*- FS
57	1		*RADIATOR AIR GUIDE - RH	Not Necessary	45.00 FS	*- FS
58	1		*RADIATOR AIR GUIDE SEAL - RH	Not Necessary	15.00 FS	*- FS
59	1		*RADIATOR AIR GUIDE - LOWER CENTRE	Not Necessary	61.00 FS	*- FS
60	1		*REAR BUMPER	Repair	2,026.00 FS	*- FS
61	1		*REAR BUMPER FIXING PARTS	Not Necessary	348.00 FS	*- FS
62	1		*REAR BUMPER LOCKING MECHANISM - RH	Not Necessary	17.00 FS	*- FS
63	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	66.00 FS	*- FS
64	1		*REAR PARKING AID SENSOR - RH	Not Necessary	286.00 FS	*- FS
65	1		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
66	1		*REAR WHEEL HOUSING LINER - RH	Not Necessary	281.00 FS	*- FS
67	1		*FRONT AND REAR ALUMINIUM RIM - RH (2PCS)	Dented (1Pc Only)	3,038.00 FS	*1,215.20 FS
68	1		*REAR ASSEMBLY CARRIER	Bent	834.00 FS	*667.20 FS
69	1		*BONDED RUBBER BUSHES	Bent	181.00 FS	*144.80 FS
70	1		*REAR WHEEL BEARING HOUSING - RH	Bent	642.00 FS	*513.20 FS
71	1		*REAR WHEEL HUB WITH BEARING	Bent	443.20 FS	*443.20 FS
72	1		*REAR GUIDE JOINT - RH	Bent	138.00 FS	*110.00 FS
73	1		*REAR COUPLING ROD	Bent	106.00 FS	*84.40 FS
74	1		*REAR JOINTED SHAFT - RH	Bent	1,548.00 FS	*1,238.40 FS
75	1		*REAR GAS SHOCK ABSORBER	Bent	469.00 FS	*374.80 FS
76	1		*REAR STEERING GEAR WITH TRACK RODS	Not Necessary	5,916.00 FS	*- FS
77	1		*REAR TRACK ROD	Bent	107.00 FS	*85.60 FS
78	1		*REAR TIE ROD END - RH	Bent	132.00 FS	*105.20 FS
79	1		*FRONT NOISE INSULATION	Not Necessary	408.00 FS	*- FS
80	1		*REAR WINDOW SLOT SEAL TRIM STRIP - RH OUTER	Not Necessary	274.00 FS	*- FS
81	1		*REAR WINDOW GUIDE TRIM STRIP - RH	Not Necessary	314.00 FS	*- FS
82	1		*FRONT NUMBER PLATE	Not Necessary	60.00 FS	*- FS
83	1		*RHS FRONT TYRE	Cut	300.00 FS	*300.00 FS
84	1		*SUNDRIES	Necessary	1,000.00 FS	*235.12 FS
85	1		*REAR LOWER CONTROL ARM - RH	Bent	396.00 FS	*316.40 FS
86	1		*AERIAL FOR ACCESS	Not Necessary	100.00 FS	*- FS
87	1		*REAR STABILIZER	Not Necessary	470.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 40,107.20 13,087.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	350.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,400.00	0.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	0.00
5	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	280.00
6	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
7	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, REAR BUMPER AND RHS HEADLIGHT. TO REPAIR RHS FRONT FENDER TOP SUPPORT, RHS FRONT DOOR AND RHS REAR FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,500.00	1,650.00
8	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT FENDER TOP SUPPORT, RHS UPPER A-PILLAR, RHS FRONT DOOR, RHS REAR FENDER AND REAR BUMPER	New	6,500.00	3,550.00
9	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,800.00	2,800.00
10	TO RENEW RHS FRONT RIM WITH TYRE AND RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	560.00	560.00
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			20,734.00	10,334.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >