



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 7584L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	SET SIDE MIRROR L/R	CRACKED	128.00	100.00
1	HEADLAMP ASSY	NOT NECESSARY	352.00	-
1	HANDLE BAR	BENT	128.00	85.00
1	SET HANDLE GRIP L/R	CRACKED	78.00	35.00
1	SET HANDLE BAR BALANCER L/R	CRACKED	68.00	30.00
1	HANDLE LEVER RH	BENT	78.00	30.00
1	HANDLE LEVER LH	NOT NECESSARY	78.00	-
1	FRONT FORK ASSY	NOT NECESSARY	622.00	-
1	FRONT WHEEL SHAFT	NOT NECESSARY	58.00	-
1	FRONT WHEEL BEARING	NOT NECESSARY	88.00	-
1	FRONT WHEEL	NOT NECESSARY	285.00	-
1	SET BODYCOVER	CRACKED	885.00	450.00
2	FRONT SIGN LAMP L/R	CUT	148.00	130.00
1	SET FRONT FOOTREST L/R	CRACKED	98.00	98.00
1	FRONT FOOTREST BRACKET	BENT	168.00	80.00
1	FRONT LH GEAR SHIFT LEVER	NOT NECESSARY	98.00	-
1	SIDE STAND	BENT	128.00	70.00
1	REAR LH FOOTREST	NOT NECESSARY	68.00	-
1	REAR LH FOOTREST BRACKET	NOT NECESSARY	128.00	-
1	SET EXHAUST PROTECTOR COVER	CRACKED	198.00	80.00
1	EXHAUST PIPE	NOT NECESSARY	428.00	-
	LESS 5% DISCOUNT		-215.50	-
	LESS 10% DISCOUNT		-	-118.80
			4,094.50	1,069.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR TOP BOX (SN)	CUT	185.00	185.00
1	SET REAR TOP BOX BRACKET / RAIL (SN)	NOT NECESSARY	80.00	-
			265.00	185.00
<b><u>LABOUR</u></b>				
	CHECK WIRING SYSTEM AND LIGHT.		80.00	30.00

Report Ref No. CS3/SMR22010711/Dwy3e2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WHEEL ALIGNMENT.		100.00	50.00
	TO CHECK, ALIGN AND BALANCE BODY MAIN FRAME.		250.00	150.00
	SPRAY PAINTING.		600.00	200.00
	LABOUR FOR REPAIR AND REPLACE PARTS.		900.00	250.00
			1,930.00	680.00
<b>GRAND TOTAL</b>			<b>6,289.50</b>	<b>1,934.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,550.00</b>

Report Ref No. CS3/SMR22010711/Dwy3e2-1

**ANG BRYAN TANI**

**Automotive Assessor / Investigator**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.