

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT HSBC LIFE (SINGAPORE) PTE LTD Ref: CS3/HSB23002362/Wnp3m4 10 MARINA BOULEVARD #48-01 MARINA BAY Date: 14/03/2023 FINANCIAL CENTRE TOWER 2 SINGAPORE ATTN: OH VALE Code: HSB Policy Particulars :- (THIRD PARTY CLAIM) 1. **SHC 2212G FBT 8962S** Insured Veh. Veh. Inspected VFX/P2419138 0.00 Policy No. Coverage (\$) S3M04K3G 0.00 Claim No. Excess (\$) 06/03/2023 OH VALE **Assign Date** Assign From Vehicle Particulars & Condition 2. CFMOTO 400GT 400 Make & Model C.C **HIDDEN Engine No.** Year of Reg. 2022 Chassis No. LCEPESL5XN6000384 Colour **BLUE** Odometer 7316 KM **IN ORDER** Steering **IN ORDER** STANDARD ALLOY RIM Modification **Brakes** GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre ADRENO SPORT 120/70 R17 6 mm L/H Front Tyre mm 160/60 R17 ADRENO SPORT R/H Rear Tyre 6 mm L/H Rear Tyre **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION AND N/S BODY. 5. **General Information** 03/03/2023 **Inspect Date / Time** 06/03/2023 (02:15 PM) **Accident Date** 25 KAKI BUKIT ROAD 4 #03-79 SINGAPORE 417800 Survey held at **EQBH PTE LTD** Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$4,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/HSB23002362/Wnp3m4

Inspected By

Asst. Automotive Assessor

MUHAMMAD AKID BIN MOHAMED KAMAL

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

DEOD Anto Organization OAE Linear Assessing

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

4 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser