

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	HSBC LIFE (SING	APORE) PTE LTD	Ref:	CS3/HSB23002363/Twp3e2	
	10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983		Date:	10/03/2023	
	ATTN: KHOR SAW	THENG	Code:	HSB	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 3053L	Veh. Inspected	SKV 5224S	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S3M04K0G	Excess (\$)	0.00	
	Assign From	KHOR SAW THENG	Assign Date	06/03/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	KIA CERATO	c.c	1999	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	KNAHU813MG7128602	Colour	WHITE	
	Odometer	125333 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	KUMHO	6 mm	
	L/H Front Tyre	225/45 R17	KUMHO	6 mm	
	R/H Rear Tyre	225/45 R17	KUMHO	6 mm	
	L/H Rear Tyre	225/45 R17	KUMHO	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
5.	General Information				
	Accident Date	28/02/2023	Inspect Date / Time	07/03/2023 ( 02:40 PM )	
	Survey held at	WEI CAR SPRAY PAINTING			
	BLK 1017 YISHUN INDUSTRIAL PARK A #01-242 SINGAPORE 768759				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$9,000				
5b.	b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days				

Report Ref No. CS3/HSB23002363/Twp3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser