

REF: Smg

ASS. REG. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / LP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: ALLIANZ

Policy No. _____

Claims No. _____

Sum Insured: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____

IDAC Accident Report: _____

GIA / PR Sent: _____

Est. Repair: 3 days

Lump Sum: 20 %

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN/OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.B.L: (\$ _____)

☐ : Prel. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation: _____

3 + RR: \$ _____

Phone: _____

Other: _____

TOTAL

Veh No: Shc 38973

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius

Colour: Blue

Sp. Reading: 257429

Eng No: _____

C/Nr: 3TDKB30U0309113

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / Airin, or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlane

Front

R/Bal: 5 mm

L/Bal: 5 mm

D.O.A: 3/3/18

Survey held at Combert

Des. of Damaged: ☒ Front / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Roof top or

The U/C / Chassis frame / Body Structure affected due to collision.