4/3/23, 8:56 AM Adjuster Report

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI23002394/SVY3Q2

03/04/2023 Date:

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MT103738 **Claimant Vehicle** 

SHC3199E Insured Vehicle No: SMC5217P No:

Date of Loss: 06/03/2023 Nature of Claim: ΤP M2301523 Claim No:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHC3199E

TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A) 2ZR2C22066 Make & Model: **Engine No:** 

Reg. Date: 29/05/2019 (Man. Year: 2018) Chassis No: JTDKB3FU903080914

Colour: Odometer: Blue 561547 km

**Engine Capacity:** 1798 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Good Yes Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition: Average

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 195/65 R15 Rear Tyre Size: Front Left Side: West Lake 5 mm Rear Left Side: West Lake 6 mm Front Right Side: West Lake 5 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,266.83	3,390.61	876.22	20.54
Miscellaneous Items		11.00	11.00	0.00	0.00
Labour		2,570.00	1,590.00	980.00	38.13
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculated Gross T	otal (S\$)	6,847.83	4,991.61	1,856.22	27.11
Approved Total (Overrido	den) (S\$)		4,000.00		
	(S\$)	6,847.83	4,000.00	2,847.83	41.59
+ GST 8.00/8.0	00% (S\$)	547.83	320.00	227.83	41.59
Nett Amo	ount (S\$)	7,395.66	4,320.00	3,075.66	41.59

**INSPECTION** 

07/03/2023 Present Location: Date of Assignment: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 07/03/2023 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqubal Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/3/23, 8:56 AM Adjuster Report

## **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Mar 2023)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC3199E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Recommended Parts

No.	Qty Pa	art No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Cracked	503.04 FL	*503.04 FL
2	1		*REAR BUMPER CENTRE MOULDING	Cracked	654.96 FL	*654.96 FL
3	1		*REAR BUMPER BEAM	Dented	318.80 FL	*318.80 FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*BOOTLID COVER	Dented	1,303.29 FL	*1,303.29 FL
6	1		*BOOTLID COVER - OUTSIDE	Cracked	1,054.71 FL	*1,054.71 FL
7	1		*BOOTLID EMBLEM - PRIUS	Necessary	62.14 FL	*62.14 FL
8	1		*BOOTLID EMBLEM - HYBRID	Necessary	62.14 FL	*62.14 FL
9	1		*BOOTLID EMBLEM - STAR	Necessary	81.43 FL	*81.43 FL
10	1		*REAR BUMPER TOW COVER	Scratched	82.70 FL	*82.70 FL
11	1		*REAR WINDSCREEN MOULDING	Not Necessary	40.40 FL	*-FL
12	1		*TAILLAMP ASSY UPPER LH	Not Necessary	557.90 FL	*- FL
13	1		*TAILLAMP ASSY LOWER LH	Not Necessary	570.00 FL	*-FL
14	1		*BOOTLID COMFORT LOGO	Necessary	30.00 F	*30.00 F
15	1		*BOOTLID COMFORT TEL.NOS LOGO	Necessary	30.00 F	*30.00 F
16	1		*BOOTLID APPS LOGO	Necessary	40.00 F	*40.00 F
17	1		*REVERSE SENSOR	Faulty	135.70 F	*135.70 F
18	1		*SEALANT	Necessary	46.00 F	*46.00 F
F=Fra	anchise par	rt. L=ListIte	mDisc.	_		
				Sub Total (S\$)	5,595.21	4,426.91
			- List Item Discount on	L Items 25.00/25.00% (S\$)	1,328.38	1,036.30
				Total Parts (S\$)	4,266.83	3,390.61

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Misc	cellan	neous Items			,
1	1	OD/TP Case (Insurer)		11.00	11.00
			Sub Total (S\$)	11.00	11.00

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,200.00	700.00
2	SPRAYPAINT	New	900.00	500.00
3	CHECK WIRING	New	50.00	30.00
4	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
5	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
6	ADVERTISEMENT LOGO- BUMPER	New	50.00	50.00
7	ADVERTISEMENT LOGO - FENDER	New	200.00	200.00
		Gross Labour Cost (S\$)	2,570.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >