

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 638581

Tel: +65 6778 3377 Email: motor@wahhong.sg

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003040780-01	Date of Loss:	03/03/2023
Vehicle Reg. No.:	SMQ6249S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MOHAMED SHAWAL BIN MOHAMED SIDEK		
Make/Model:	KIA CERATO, 1.6 EX (A)	Vehicle Reg. Date:	27/11/2019
Vehicle Colour:	SILVER	Chassis No:	KNAF3416MK5047522
Engine No:	G4FGKH741950		
Odometer:	62851 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	7,155.50
Miscellaneous Items	350.00
Labour	3,040.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,545.50
+ GST 8.00% (S\$)	843.64
Nett Amount (S\$)	11,389.14

This claim is handled by: TAN TING YI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Mar 2023)
 Parts: 143 KIA CERATO 1.6 EX (A) (Catalytic Converter Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Wah Hong Motors & Credit Pte Ltd/SMQ6249S/06/03/2023 18:53
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Bonnet <i>bn</i> ✓	0.00	0.00	*750.00 F
2	1		*Bonnet hinge RH/LH@2*\$30 <i>bt</i> ✓	0.00	0.00	*60.00 F
3	1		*Bonnet insulator <i>di</i> ✓	0.00	0.00	*80.00 F
4	1		*Bonnet stand holder <i>Mls</i> ✓	0.00	0.00	*2.00 F
5	1		*Bonnet lock <i>bt</i> ✓	0.00	0.00	*60.00 F
6	1		*Wiper top garnish <i>scr</i> ✓	0.00	0.00	*110.00 F
7	1		*Wiper top side garnish RH/LH@2*\$8 <i>ms/de</i> ✓	0.00	0.00	*16.00 F
8	1		*Front fender RH/LH@2*\$220 <i>RH-bnc/LH-rpmv</i>	0.00	0.00	*440.00 F
9	1		*Front fender shield RH <i>X</i>	0.00	0.00	*40.00 F
10	1		*Headlamp RH/LH@2*\$650 <i>ca</i> ✓	0.00	0.00	*1,300.00 F
11	1		*Front bumper <i>tom</i> ✓	0.00	0.00	*260.00 F
12	1		*Front bumper side retainer RH/LH@2*\$15 <i>RH-ca/LH-X</i>	0.00	0.00	*30.00 F
13	1		*Front bumper logo badge <i>m</i> ✓	0.00	0.00	*20.00 F
14	1		*Front bumper center grille <i>ca</i> ✓	0.00	0.00	*130.00 F
15	1		*Front bumper towing cover <i>de</i> ✓	0.00	0.00	*5.00 F
16	1		*Front bumper lower grille <i>ca</i> ✓	0.00	0.00	*170.00 F
17	1		*Day lamp RH/LH@2*\$65 <i>RH-?/LH-X</i>	0.00	0.00	*130.00 F
18	1		*Day lamp cover RH/LH@2*\$25 <i>RH-?/LH-X</i>	0.00	0.00	*50.00 F
19	1		*Fog lamp RH/LH@2*\$120 <i>X</i>	0.00	0.00	*240.00 F
20	1		*Radiator top garnish <i>ca</i> ✓	0.00	0.00	*28.00 F
21	1		*Front bumper sponge <i>ca</i> ✓	0.00	0.00	*45.00 F
22	1		*Front reinforcement <i>?</i>	0.00	0.00	*200.00 F
23	1		*Front lower reinforcement <i>X</i>	0.00	0.00	*50.00 F
24	1		*Front bumper inner side garnish RH/LH@2*\$13 <i>RH-?/LH-X</i>	0.00	0.00	*26.00 F
25	1		*Support panel <i>ca</i> ✓	0.00	0.00	*330.00 F
26	1		*Condenser <i>bt</i> ✓	0.00	0.00	*400.00 F
27	1		*Radiator <i>bt</i> ✓	0.00	0.00	*300.00 F
28	1		*Radiator air guide RH/LH@2*\$15 <i>RH-ca/LH-X</i>	0.00	0.00	*30.00 F
29	1		*Fan cowling <i>ca</i> ✓	0.00	0.00	*350.00 F
30	1		*Wiper tank <i>ca</i> ✓	0.00	0.00	*65.00 F
31	1		*Throttle body <i>X</i>	0.00	0.00	*360.00 F
32	1		*Engine oil gauge <i>X</i>	0.00	0.00	*28.00 F
33	1		*Intake manifold <i>ca</i> ✓	0.00	0.00	*400.00 F
34	1		*Front door RH (repair refer to labour)	0.00	0.00	*- F

F=Franchise part.

Sub Total (S\$)	6,505.00
+ Margin on L,N Items 10.00% (S\$)	650.50
Total Parts (S\$)	7,155.50

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Bonnet insulator clip <i>M</i>	25.00 ✓
2	1	Coolant <i>M</i>	50.00 30
3	1	Front bumper center grille clip <i>M</i>	25.00 ✓
4	1	Front bumper clip <i>M</i>	35.00 30
5	1	Front carplate with holder <i>st</i>	35.00 ✓
6	1	Front fender shield clip RH <i>M</i>	25.00 20
7	1	Headlamp lightbulb RH <i>M</i>	100.00 X
8	1	Headlamp signal lightbulb RH <i>X</i>	30.00 X
9	1	Radiator top garnish clip <i>M</i>	25.00 20
Sub Total (S\$)			350.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	1,400.00 1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	1,400.00 1000
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	60.00 30
4	Remove and refit aircon condenser, radiator, related pipes and hoses, vacuum and refill aircon gas	New	100.00 ✓
5	Re-sealing of Off peak car licence plate at LTA, including inspection fee	New	80.00 ✓
Gross Labour Cost (S\$)			3,040.00

Wah Hong Motors & Credit Pte Ltd/SMQ6249S/06/03/2023 18:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rame
Hp 90010068
7 days
P/P
07/03/23 @ 16/10
EXCESS: 2000
Revert
Resy before paint