

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23002402/HQY3M4**Date:** 19/06/2023**REFERENCE**

Insured/Claimant:	AMRAN BIN ATAN	Policy No:	SP2001808782-01	
Date of Loss:	03/03/2023	Nature of Claim:	OD	Claim No: 202332005908

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF8906Y	Engine No:	2AZF162812
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Chassis No:	ACR507063792
Reg. Date:	15/10/2008 (Man. Year: 2008)	Odometer:	176237 km
Colour:	White		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	S\$68,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Firenza 4 mm	Rear Left Side:	Firenza 4 mm
Front Right Side:	Firenza 4 mm	Rear Right Side:	Firenza 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,522.00	1,844.50	1,677.50	47.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	1,030.00	780.00	43.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,332.00	2,874.50	2,457.50	46.09
Approved Total (Overridden) (S\$)		2,250.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	5,332.00	1,650.00	3,682.00	69.05
+ GST 8.00/8.00% (S\$)	426.56	132.00	294.56	69.05
Nett Amount (S\$)	5,758.56	1,782.00	3,976.56	69.05

INSPECTION

Date of Assignment:	07/03/2023 Present Location:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected:	07/03/2023 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair:	4.0 days	

Adjuster: Edward**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2023)
Parts:	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF8906Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Cut	35.00 FS	*35.00 FS
2	1		*FRT BUMPER (WCP)	Dented	240.00 F	*240.00 F
3	2		*FRT BUMPER RETAINER (WCP)	Not Necessary	90.00 F	*- F
4	1		*FRT BUMPER LWR GRILLE (WCP)	Cut	90.00 F	*90.00 F
5	1		*FRT BUMPER LWR OUTER CHROME TRIM (WCP)	Cracked	140.00 F	*140.00 F
6	1		*FRT BUMPER UPPER TOP BEAM (WCP)	Not Necessary	150.00 F	*- F
7	1		*FRT BUMPER SPONGE (WCP)	Not Necessary	60.00 F	*- F
8	1		*FRT BUMPER REINFORCEMENT (WCP)	Dented	150.00 F	*150.00 F
9	1		*FRT BUMPER TOP SEAL (WCP)	Not Necessary	45.00 F	*- F
10	10		*FRT BUMPER CLIP (WCP)	Necessary	10.00 F	*10.00 F
11	1		*FRT GRILLE ASSY (WCP)	Cracked	190.00 F	*190.00 F
12	1		*FRT GRILLE EMBLEM (WCP)	Distorted	45.00 F	*45.00 F
13	10		*FRT GRILLE CLIP (WCP)	Necessary	20.00 F	*20.00 F
14	1		*FRT BONNET (WCP)	Buckled	240.00 F	*240.00 F
15	2		*FRT BONNET HINGE (WCP)	Not Necessary	80.00 F	*- F
16	10		*FRT BONNET INSULATOR CLIP (WCP)	Necessary	20.00 F	*20.00 F
17	2		*FRT HEADLAMP (WCP)	Not Necessary	1,100.00 F	*- F
18	1		*AIRCON CONDENSER (WCP)	Punctured	500.00 F	*500.00 F
F=Franchise part. S=SpcNett.						
Sub Total (S\$)					3,205.00	1,680.00
+ Margin on L,N Items 10.00/10.00% (S\$)					317.00	164.50
Total Parts (S\$)					3,522.00	1,844.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	750.00	400.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED ARAES	New	750.00	500.00
3	CHECK WIRING	New	30.00	30.00
4	TOP UP AIRCON GAS	New	100.00	100.00
5	TO DIAGNOSE & RESET FAULT CODE	New	180.00	0.00
Gross Labour Cost (S\$)			1,810.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >