

REF C86/AIS23002402/Hcy3

Desktop Survey

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 8600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$68,000

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKF 8906Y Yr Regn: 15/10/2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA ESTIMA AERAS 2362

Colour: WHITE ? 2-4 A/C: Insured / Std / NI / NA

Sp. Reading: 176237 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACR507063792*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50 R18 ✓

R: W

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FIRENZA

Front: _____ Rear: _____

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 3/3/2023 D.O.I. _____

Survey held at DESKTOP SURVEY ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	NET VALUE <u>\$49,000</u>
	Finalised LS <u>\$2250</u> , 4 days. (Red <u>\$3082</u> , 58%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS SI

Photos

Others

TOTAL

Report Format: NET-00

Lump Sum / I.B.A. (\$ 2250)

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001808782-01	Date of Loss:	03/03/2023
Vehicle Reg. No.:	SKF8906Y	Driveable?	
Driver Age/Info:	54 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	AMRAN BIN ATAN	Contact No:	+6591762926
Driver:	AMRAN BIN ATAN		

Make/Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Vehicle Reg. Date:	15/10/2008
Vehicle Colour:	White	Chassis No:	ACR507063792
Engine No:	2AZF162812		
Odometer:	5 KM		

Paint Type:

Total Loss? NO

Est. Duration of Repair (day) 6 4

Description of Accident/Loss AS PER POLICE RE

Remarks: VEHICLE IN WORKSHOP, PLS ARRANGE TO SURVEY

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS	Amount
Parts	3,522.00
Miscellaneous Items	0.00
Labour	1,810.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,332.00
+ GST 8.00% (S\$)	426.56
Nett Amount (S\$)	5,758.56

This claim is handled by: SAMANTHA TAN YONG SING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Mar 2023)
 Parts: M1-MPV TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SKF8906Y/06/03/2023 15:20
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	✓	0	*35.00 FS
2	1		*FRT BUMPER	✓	0.00	*240.00 F
3	2		*FRT BUMPER RETAINER	✓	0.00	*240.00 F
4	1		*FRT BUMPER LWR GRILLE	✓	0.00	*90.00 F
5	1		*FRT BUMPER LWR OUTER CHROME TRIM	✓	0.00	*90.00 F
6	1		*FRT BUMPER UPPER TOP BEAM	✓	0.00	*140.00 F
7	1		*FRT BUMPER SPONGE	✓	0.00	*150.00 F
8	1		*FRT BUMPER REINFORCEMENT	✓	0.00	*60.00 F
9	1		*FRT BUMPER TOP SEAL	✓	0.00	*150.00 F
10	10		*FRT BUMPER CLIP	✓	0.00	*45.00 F
11	1		*FRT GRILLE ASSY	✓	0.00	*10.00 F
12	1		*FRT GRILLE EMBLEM	✓	0.00	*190.00 F
13	10		*FRT GRILLE CLIP	✓	0.00	*45.00 F
14	1		*FRT BONNET	✓	0.00	*20.00 F
15	2		*FRT BONNET HINGE	✓	0.00	*240.00 F
16	10		*FRT BONNET INSULATOR CLIP	✓	0.00	*80.00 F
17	2		*FRT HEADLAMP	✓	0.00	*20.00 F
18	1		*AIRCON CONDENSER	✓	0.00	*1,100.00 F
				✓	0.00	*500.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 3,205.00
 + Margin on L,N Items 10.00% (\$\$) 317.00

Total Parts (\$\$) 3,522.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF8906Y/06/03/2023 15:20. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	✓ New	400 750.00 ✓
2	TO PUTTY & SPRAY PAINTING ON AFFECTED ARAES	✓ New	500 750.00 ✓
3	CHECK WIRING	✓ New	30.00 ✓
4*	TOP UP AIRCON GAS	✓ New	100.00 ✓
5	TO DIAGNOSE & RESET FAULT CODE	New	180.00 XNN
Gross Labour Cost (S\$)			1,810.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF8906Y/06/03/2023 15:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 4 DAYS

- NOT AUTHORISE
- EXCESS \$600 ✓
- P/P OR L/S REPAIR
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: