

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS23002410/KVY3Q2**Date:** 24/05/2023**REFERENCE**

Insured/Claimant:	CHOW FOOK HING	Policy No:	SP2001555549
Date of Loss:	04/03/2023	Nature of Claim:	OD
		Claim No:	202332005940

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM7789B	Engine No:	2ZR2C94444
Make & Model:	TOYOTA VOXY, 2.0 ZS CVT (A)	Chassis No:	ZWR800374212
Reg. Date:	25/04/2019 (Man. Year: 2019)	Odometer:	93227 km
Colour:	Metallic Pearl White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	S\$139,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,839.32	4,491.00	7,348.32	62.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,540.00	1,690.00	52.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,069.32	6,031.00	9,038.32	59.98
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	14,469.32	5,431.00	9,038.32	62.47
+ GST 8.00/8.00% (S\$)	1,157.55	434.48	723.07	62.47
Nett Amount (S\$)	15,626.87	5,865.48	9,761.39	62.47

INSPECTION

Date of Assignment: 07/03/2023

Date Inspected: 08/03/2023 Inspected At:

Estimated Period of Repair: 5.0 days

176 SIN MING DRIVE
#01-14 SIN MING AUTOCARE
SINGAPORE 575721
Repairer: Esteem Performance Pte Ltd - Sin Ming (HQ)**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2023)
Parts: M1-MPV	TOYOTA VOXY 2.0 ZS CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLM7789B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Shattered	1,336.60 FL	*1,336.60 FL
2	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
3	1		*REAR WINDSCREEN MOULDING (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*REVERSE SENSOR	Dented	736.20 FS	*200.00 FS
5	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
6	1		*REAR NO PLATE LAMP LH	Serviceable	69.10 FL	*- FL
7	1		*REAR NO PLATE LAMP RH	Serviceable	69.10 FL	*- FL
8	1		*REAR NO PLATE GARNISH	No such part	896.60 FL	*- FL
9	1		*REAR BUMPER	Bent	1,497.80 FL	*798.20 FL
10	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
11	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	170.00 FL	*- FL
12	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	170.00 FL	*- FL
13	1		*REAR BUMPER BRACKET LH	Serviceable	84.70 FL	*- FL
14	1		*REAR BUMPER BRACKET RH	Repair	84.70 FL	*- FL
15	1		*REAR BUMPER REFLECTOR LH	Serviceable	63.40 FL	*- FL
16	1		*REAR BUMPER REFLECTOR RH	Serviceable	63.40 FL	*- FL
17	1		*REAR BUMPER TOW COVER	Serviceable	25.30 FL	*- FL
18	1		*TAIL DOOR	Bent	1,919.30 FL	*1,812.10 FL
19	1		*TAIL DOOR LOCK	Repair	495.40 FL	*- FL
20	1		*TAIL DOOR EMBLEM	Necessary	71.60 FL	*71.60 FL
21	1		*WORDING HYBRID SYNERGY	Necessary	50.80 FL	*50.80 FL
22	1		*TAIL DOOR CHROME	Cracked	1,018.60 FL	*873.10 FL
23	1		*TAIL DOOR TRIM	Serviceable	605.10 FL	*- FL
24	10		*TAIL DOOR TRIM CLIP	Not Necessary	50.00 FL	*- FL
25	1		*REAR WIPER MOTOR	Serviceable	818.10 FL	*- FL
26	1		*REAR WIPER BLADE	Serviceable	57.80 FL	*- FL
27	1		*THIRD BRAKE LIGHT	Serviceable	227.60 FL	*- FL
28	1		*TAIL END PANEL	Repair	779.40 FL	*- FL
29	1		*TAIL END PANEL GARNISH	Buckled	162.50 FL	*162.50 FL
30	10		*TAIL END PANEL GARNISH CLIP	Necessary	50.00 FL	*50.00 FL
31	1		*BOOT WEATHERSTRIP	Cut	394.70 FL	*394.70 FL
32	1		*TAIL LAMP LH	Serviceable	706.10 FL	*- FL
33	1		*TAIL LAMP RH	Serviceable	706.10 FL	*- FL
34	1		*SPARE TYRE WELL PANEL	Repair	739.90 FL	*- FL
35	1		*SPARE TYRE BOARD	Serviceable	1,175.40 FL	*- FL
36	1		*REAR WIPER BLADE	Cracked	68.40 FL	*68.40 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,508.70	5,908.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,669.38	1,417.00
Total Parts (\$\$)	11,839.32	4,491.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (TAILDOOR,REAR BUMPER END PANEL,SPARE TYRE WELL PANEL)	New	1,200.00	550.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (TAILDOOR,REAR BUMPER ,END PANEL ,SPARE TYRE WELL PANEL)	New	1,200.00	660.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	120.00	50.00
5	TO TUFF COAT	New	150.00	0.00
6	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
7	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	60.00
8	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	60.00
9	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	20.00
			Gross Labour Cost (S\$)	3,230.00
				1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >