



ESTEEM

ESTEEM PERFORMANCE PTE LTD
 UEN 200005485N
 HEADQUARTERS / SHOWROOM / WORKSHOP
 385 Sin Ming Drive
 Singapore 575718
 (T) 6753 2112 (F) 6451 0394
 WORKSHOP
 176 Sin Ming Drive
 Sin Ming Auto Care #01-14, #01-15, #01-16
 Singapore 575721
 (T) 6484 1221 (F) 6484 7829

Repair Estimates

SLM 7789 B

*NOT AUTHORIZED
 Resurvey By paint
 Ex @ 600*

Parts (a) Cost / List Price Items	\$	<u>15,590.70</u>
Plus/Less 25%	\$	<u>3,897.68</u>
Total of Cost / List	\$	<u><u>11,693.03</u></u>
(b) Nett Price Items		_____
Less		_____
Total of Nett Item		_____
(c) Special Nett Items	\$	<u>95.00</u>
Total Parts Cost	\$	<u><u>11,788.03</u></u>
Labour	\$	<u><u>3,230.00</u></u>
Total	\$	<u><u>15,018.03</u></u>

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Henrich

Company : CKC

Survey conducted on : 8/3/23 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 5-6 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ 600

(e) Signature of surveyor : De Date: 8/3/23



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200006485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : _____
Make & Model : SLM 7789 B
 : TOYOTA VOXY
Chassis No : ZWR800374212

Submit By : _____
Year Manufacture : 2019 Apr
Engine No. : _____
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen <i>Shattered</i>	1	\$1,336.60		✓
2	Rear windscreen moulding	1			
3	Rear windscreen sealant <i>Ma</i>	1	\$50.00	S.N	<i>Goja</i>
4	Reverse sensor	2	\$981.60		?
5	Rear number plate <i>Pu</i>	1	\$45.00	S.N	X
6	Rear No.plate lamp LH <i>Pu</i>	1	\$69.10		X
7	Rear No.plate lamp RH <i>Lu</i>	1	\$69.10		X
8	Rear No.plate garnish <i>NSP GAA</i>	1	\$896.60		X
9	Rear bumper <i>Ry</i>	1	\$1,497.80		✓
10	Rear bumper clip <i>Ma</i>	10	\$50.00		✓
11	Rear bumper side retainer LH <i>Pu</i>	1	\$170.00		✓
12	Rear bumper side retainer RH <i>Lu</i>	1	\$170.00		X
13	Rear bumper bracket LH <i>Pu</i>	1	\$84.70		X
14	Rear bumper bracket RH	1	\$84.70		?
15	Rear bumper reflector LH <i>Lu</i>	1	\$63.40		✓
16	Rear bumper reflector RH <i>Lu</i>	1	\$63.40		X
17	Rear bumper tow cover <i>Pu</i>	1	\$25.30		X
18	Tail door <i>Ry</i>	1	\$1,919.30		✓
19	Tail door lock	1	\$495.40		?
20	Tail door emblem <i>Ma</i>	1	\$71.60		✓
21	Wording "hybrid synergy" <i>Ma</i>	1	\$50.80		✓
22	Tail door chrome <i>CM</i>	1	\$1,018.60		✓
23	Tail door trim	1	\$605.10		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No :

SLM 7789 B

TOYOTA VOXY
 ZWR800374212

Submit By :
 Year Manufacture :
 Engine No. :

Carmen Lim
 2019 Apr

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door trim clip <i>na</i>	10	\$50.00		X
25	Rear wiper motor <i>pu</i>	1	\$818.10		X
26	Rear wiper blade <i>pu</i>	1	\$57.80		X
27	Third brake light <i>pu</i>	1	\$227.60		X
28	Tail end panel	1	\$779.40		?
29	Tail end panel garnish <i>pu</i>	1	\$162.50		✓
30	Tail end panel garnish clip <i>na</i>	10	\$50.00		✓
31	Boot weatherstrip <i>pu</i>	1	\$394.70		✓
32	Tail lamp LH <i>pu</i>	1	\$706.10		X
33	Tail lamp RH <i>pu</i>	1	\$706.10		X
34	Spare tyre well panel <i>R</i>	1	\$739.90		X
35	Spare tyre board <i>pu</i>	1	\$1,175.40		X
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : SLM 7789 B
Make & Model : TOYOTA VOXY

Submit By : Carmen Lim
Year of Manufacture : 2019 Apr

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(TAILDOOR,REAR BUMPER,END PANEL,SPARE TYRE WELL PANEL)	\$1,200.00	?
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(TAILDOOR,REAR BUMPER,END PANEL,SPARE TYRE WELL PANEL)	\$1,200.00	660
3	To check wiring	\$50.00	200
4	To remove & refit reverse sensor	\$120.00	500
5	To tuff coat NZ	\$150.00	X
6	To remove & refit rear windscreen	\$120.00	✓
7	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	600
8	To transfer boot mechanism to new boot	\$120.00	600
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	200

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.