



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 4373G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	1,028.00	-
1	REAR BUMPER REFLECTORS RH	NOT NECESSARY	68.00	-
2	REAR BUMPER SIDE RETAINER @\$55.00	NOT NECESSARY	110.00	-
1	REAR FENDERS RH	TO REPAIR SEE LABOUR	1,391.00	-
1	REAR FENDER INNER TRIMS RH	NOT NECESSARY	399.00	-
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	374.40	-
1	FRONT KNUCKLE ARM RH	NOT NECESSARY	390.20	-
1	FRONT WHEEL BEARING RH	NOT NECESSARY	147.70	-
1	FRONT WHEEL BEARING HUB RH	NOT NECESSARY	245.00	-
1	FRONT LOWER ARM RH	NOT NECESSARY	350.00	-
1	REAR DOOR RH	NOT NECESSARY	1,717.50	-
1	REAR DOOR FRAME BLACK RH	NOT NECESSARY	75.90	-
1	REAR DOOR INNER LOCK RH	NOT NECESSARY	819.70	-
2	REAR DOOR BOTTOM HINGE	NOT NECESSARY	191.60	-
1	REAR DOOR OUTER HANDLE RH	NOT NECESSARY	215.00	-
1	REAR DOOR RUBBER	NOT NECESSARY	217.00	-
1	REAR DOOR GLASS REGULATOR MOTOR RH	NOT NECESSARY	435.00	-
1	REAR DOOR GLASS REGULATOR RH	NOT NECESSARY	688.40	-
1	REAR DOOR BOARD RH	NOT NECESSARY	918.70	-
1	REAR DOOR CHECKER RH	NOT NECESSARY	85.90	-
1	SIDE SKIRT RH	NOT NECESSARY	1,200.00	-
1	TAIL LAMPS RH	NOT NECESSARY	589.00	-
1	TAIL LAMP HOUSING PANELS RH	NOT NECESSARY	345.00	-
	LESS 10% DISCOUNT		-1,200.20	-
			10,801.80	-
<u>SPECIAL NETT ITEMS</u>				
1	SPORT RIM REAR O/S (SN)	CUT / CRUMPLED	1,500.00	500.00
1	TYRE O/S (SN)	NOT NECESSARY	500.00	-
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	80.00	-

Report Ref No. CS/INC23002420/Uwy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER CLIPS (SN)	NOT NECESSARY	80.00	-
			2,160.00	500.00
	LABOUR			
	TO CHECK WIRING.	NOT NECESSARY	80.00	-
	TO DISMANTLE & REPLACED REVERSE SENSOR.	NOT NECESSARY	150.00	-
	TO CONDUCT WHEEL ALIGNMENT.		350.00	60.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		150.00	80.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	250.00	-
	LABOUR FOR PANEL BEATING & REPLACE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR FENDERS RH.		1,800.00	350.00
	TO PUTTY & SPRAY PAINTING.		1,600.00	400.00
			4,380.00	890.00
GRAND TOTAL			17,341.80	1,390.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,100.00

Report Ref No. CS/INC23002420/Uwy3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.