

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI23002424/ACY3Q2
Date: 18/07/2023**REFERENCE**

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SJV2424M	Insured Vehicle No :	SMU8440X
Date of Loss:	04/03/2023	Nature of Claim:	TP
		Claim No:	CDMPG23000553

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV2424M	Engine No:	KMHDU41BMAU897972
Make & Model:	ADIVA AD1 200, 190cc 3W	Chassis No:	G4FC9U751427
Reg. Date:	18/01/2010 (Man. Year: 2019)	Odometer:	225925 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,006.00	2,232.00	2,774.00	55.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,440.00	1,160.00	280.00	19.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,446.00	3,392.00	3,054.00	47.38
Approved Total (Overridden) (S\$)		2,700.00		
Nett Amount (S\$)	6,446.00	2,700.00	3,746.00	58.11

INSPECTION

Date of Assignment:	07/03/2023	
Date Inspected:	17/04/2023	Inspected At: Tk Motor Workshop (HQ) Blk 1 Kaki Bukit Ave 6 #02-56, Autobay @ Kaki Bt Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Jul 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV2424M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	908.00 F	*908.00 FL
2	1		*REAR BOOTLID LOCK	Damaged	90.00 F	*90.00 FL
3	1		*REAR BOOTLID INNER TRIMBOARD	Not Necessary	278.00 F	*- FL
4	12		*REAR BOOTLID INNER TRIMBOARD CLIP	Not Necessary	33.00 F	*- FL
5	2		*REAR BOOTLID REFLECTOR LAMP	Not Necessary	624.00 F	*- FL
6	3		*REAR BOOTLID EMBLEM	Necessary	189.00 F	*189.00 FL
7	1		*REAR TAILLAMP	N/S Cracked	550.00 F	*275.00 FL
8	1		*REAR END PANEL	Repair	560.00 F	*- FL
9	1		*REAR END PANEL GARNISH	Deformed	58.00 F	*58.00 FL
10	1		*REAR BUMPER	Deformed	532.00 F	*532.00 FL
11	1		*REAR BUMPER SPONGE	Cracked	115.00 F	*115.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Cracked	240.00 F	*240.00 FL
13	5		*REAR BUMPER BRACKET	Damaged	85.00 F	*85.00 FL
14	8		*REAR BUMPER CLIP	Necessary	32.00 F	*32.00 FL
15	1		*SET REVERSE SENSOR	Necessary	200.00 FS	*200.00 FS
16	1		*REAR BOOTLID RUBBER	Not Necessary	116.00 F	*- FL
17	1		*REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
18	4		*REAR END PANEL GARNISH CLIP	Necessary	16.00 F	*16.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,006.00	2,740.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	508.00
Total Parts (\$)	5,006.00	2,232.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY PAINTING	New	600.00	500.00
3	TO REMOVE AND REFIX REAR INTERIOR UPHOLSY & CUSHION	New	80.00	40.00
4	TO LABOUR CHARGE FOR PANEL BEATING ,WELDING ,REMOVING OF ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC	New	550.00	500.00
5	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	New	80.00	40.00
6	TO MEASURE DRILL THE REPLACED BUMPER ,POSITION & REINSTALL REAR REVERSE SENSOR ,CONTROL UNIT,REVERSE CAMERA CHECK & TEST FOR FUNCTIONING	New	80.00	50.00
Gross Labour Cost (S\$)			1,440.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >