



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI23002426/Uny3e2	
			Date: 22/03/2023	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 3542T	Veh. Inspected	XD 5932Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	D23000783MFBP	Excess (\$)	0.00
	Assign From	JOANNE TAN JO ANN	Assign Date	06/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI FV51 TMA (M)	c.c	12882
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	FV51JJA00847	Colour	GREEN
	Odometer	358861 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	AGATE	7 mm
	L/H Front Tyre	295/80 R22.5	AGATE	7 mm
	R/H Rear Tyre	295/80 R22.5 (D/D)	DOUPRO	7/7/7/7 mm
	L/H Rear Tyre	295/80 R22.5 (D/D)	DOUPRO	7/7/7/7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/03/2023	Inspection Date	07/03/2023
	Survey held at	MAH LIAN MOTOR VEHICLE REPAIRER 38 DEFU LANE 9 SINGAPORE 539278		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	