

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 8151P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	BENT	976.80	633.00
1	FRONT BUMPER	BUCKLED	901.70	561.20
1	FRONT BUMPER SIDE RETAINER RH	CRACKED	18.40	18.40
20	FRONT BUMPER CLIPS @\$3.00	NECESSARY	60.00	60.00
1	FRONT BUMPER CENTRE GRILLE SIDE MOULDING RH	DENTED	51.00	51.00
1	FRONT RADIATOR GRILLE	CRACKED	343.40	343.40
1	FRONT GRILLE TOP CHROME MOULDING	CRACKED	232.80	232.80
1	FRONT GRILLE MOULDING	DENTED	249.40	249.40
1	FRONT GRILLE LOGO EMBLEM	NECESSARY	27.40	27.40
1	FRONT FENDER INNER SHIELD RH (CRACKED)	NOT CONSISTENT WITH THE IMPACT	110.50	-
1	FRONT NUMBER PLATE BASE	DENTED	85.40	85.40
1	FRONT HEADLAMP LOWER BEAM LH	TO REPAIR SEE LABOUR	44.70	-
1	AIRCON CONDENSER (ADDITIONAL)	PUNCTURE	704.40	704.40
1	FRONT BUMPER REINFORCEMENT (ADDITIONAL)	BENT	320.90	320.90
1	RADIATOR GRILLE CENTRE BRACKET (ADDITIONAL)	BENT	35.70	35.70
	LESS 20% DISCOUNT		-832.50	-664.60
			3,330.00	2,658.40
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
			35.00	35.00
	LABOUR			
	TO STRAIGHTEN FRONT BODY ,TO KNOCK DENTS ON FRONT SUPPORT PANEL AND RENEW OF PARTS.INCLUSIVE OF THE REPAIR OF FRONT HEADLAMP LOWER BEAM LH .		400.00	400.00
	TO SPRAY PAINT.		600.00	500.00
			1,000.00	900.00
	GRAND TOTAL	†	4,365.00	3,593.40

Report Ref No. CS/AGI23002427/Kny3q2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			3,593.40
-----------------------------	--	--	----------

Report Ref No. CS/AGI23002427/Kny3q2

KONG SENG CHEONG

Licensed Appraiser