

ASS. REC. BY:

REF:

AK2/23002427/Kny3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

10-30am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 862K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1.131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PMX 8151P Yr Regn: 05, 18Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Honda Jazz c.c. 1318Colour M. Yellow A/C: ☐ Insured / ☐ Std / ☐ Nil / ☐ NASp. Reading 103307 T/Radio: ☐ Insured / ☐ Std / ☐ Nil / ☐ NA

Eng/No: _____

C/No: JHMGK 38 503X 217613Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ Nil / ☐ S/Rlm / ☐ STD A/Rlm or

Tyre Size: F: _____

R: 205/45R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 5/3/23

Survey held at

Rear

R/Bal. 4 mmL/Bal. 4 mmD.O.A. 17/3/2023Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/3 @ 3593.40 C/LW (Red. \$ 771.60, 18%)

Date/Time, File Pass to?

☐ : Prell. ReportDays Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

ESTIMATE

EST. No: EST0031557
Boh Qi Jie Ryan Nathan

Page: 1 of 2
Your ref.: TP-SLT 2314J AGI
Job No.: 73430
Our ref: 23.03.09
Payment
Date: 7/3/2023

Attn

Vehicle No: SMX 8151P
Vehicle Model : Honda Jazz
Accident on ...: 5/3/2023

Not Notch
Heavy B4 paint

83593.40

4 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Bonnet <i>633</i>	976.80	20.00	<i>B1</i> 781.44 ✓
1.00	Pc	Front bumper <i>561-20</i>	901.70	20.00	<i>Bu</i> 721.36 ✓
1.00	Pc	Front bumper side retainer RH	18.40	20.00	<i>cm</i> 14.72 ✓
20.00	Pcs	Front bumper clips	3.00	20.00	<i>mc</i> 48.00 ✓
1.00	Pc	Front bumper centre grille side moulding RH	51.00	20.00	<i>nd</i> 40.80 ✓
1.00	Pc	Front radiator grille	343.40	20.00	<i>cm</i> 274.72 ✓
1.00	Pc	Front grille top chrome moulding	232.80	20.00	<i>cm</i> 186.24 ✓
1.00	Pc	Front grille moulding	249.40	20.00	<i>nc</i> 199.52 ✓
1.00	Pc	Front grille logo emblem	27.40	20.00	<i>nc</i> 21.92 ✓
1.00	Pc	Front fender inner shield RH <i>n.c (cm)</i>	110.50	20.00	88.40 ✓
1.00	Pc	Front number plate base	85.40	20.00	<i>nc</i> 68.32 ✓
1.00	Pc	Front headlamp lower beam LH	44.70	20.00	<i>nc</i> 35.76 ✓
Special nett item:					
1.00	Pc	Front number plate	35.00		<i>B1</i> 35.00 ✓

Labour & Misc:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature
Date:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0031557
Boh Qi Jie Ryan Nathan

Page: 2 of 2
Your ref.: TP-SLT 2314J AGI
Job No.: 73430
Our ref.: 23.03.09
Payment
Date: 7/3/2023

Attn

Vehicle No: SMX 8151P
Vehicle Model : Honda Jazz
Accident on ...: 5/3/2023

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To straighten front body, to knock dents on front support panel and renew of parts	400.00		400.00 ✓
1.00		To spray paint	600.00		600.00 ^{50d}

Sub-Total 4365
GST 8.00% 3,516.20
Total 281.30
S\$ 3,797.50

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 5267

GST No: M2-0128609-3

UEN: 199407592C

SUPPLEMENTARY

ESTIMATE

EST. No : EST0031557
Boh Qi Jie Ryan Nathan

Page : 1 of 1
Your ref. : TP-SLT 2314J AGI
Job No. : 73430
Our ref. : 23.03.10
Payment :
Date : 19/4/2023

Attn :

Vehicle No : SMX 8151P
Vehicle Model : Honda Jazz
Accident on : 5/3/2023

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
SUPPLEMENTARY:					
1.00	Pc	Aircon condenser	704.40	20.00	563.52
1.00	Pc	Front bumper reinforcement	320.90	20.00	256.72
1.00	Pc	Radiator grille centre bracket	35.70	20.00	28.56

Sub-Total 848.80
GST 8.00% 67.90
Total S\$ 916.70

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
此外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."