3/21/23, 12:07 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG23002429/AYA3Q2

21/03/2023 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220102142 **Claimant Vehicle** SMT5042L Insured Vehicle No: SJL8479T

No:

Date of Loss: 05/03/2023 Nature of Claim: TP Claim No: 2466993465SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMT5042L

HONDA JAZZ, 1.3 CVT (A) Make & Model: L13B15000693 Engine No: Reg. Date: 23/06/2020 (Man. Year: 2020) Chassis No: JHMGK3850LS217913

Colour: White Odometer: 33872 km

Engine Capacity: 1318 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 175/65 R15 Rear Tyre Size: Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,232.72	2,729.28	1,503.44	35.52
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,980.00	2,800.00	1,180.00	29.65
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,212.72	5,529.28	2,683.44	32.67
	Approved Total (Overridden) (S\$)		4,400.00		
	Nett Amount (S\$)	8,212.72	4,400.00	3,812.72	46.42
	Global Sum	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 07/03/2023

JDM AUTOCARE (HQ)

1 KAKI BUKIT AVENUE 6 #01-51, Autobay @ Kaki Date Inspected: 07/03/2023 Inspected At:

Bukit

Singapore 417883

Estimated Period of Repair: 8.0 days

ADRIAN LING Manager: Adjuster: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLIGHT ASSY R	Cut	358.40 FL	*358.40 FL
2	1		*LIGHT ASSYR LID	Not Necessary	194.20 FL	*- FL
3	1		*TAILGATE COMP	Dented	782.10 FL	*782.10 FL
4	1		*WEATHERSTRIP TAILGATE	Not Necessary	192.30 FL	*- FL
5	1		*LOCK ASSY TAILGATE	Damaged	191.10 FL	*191.10 FL
6	1		*HANDLE TAILGATE	Not Necessary	64.70 FL	*- FL
7	1		*EMBLEMRR	Necessary	95.00 FL	*95.00 FL
8	1		*FACE RR BUMPER	Deformed	596.90 FL	*596.90 FL
9	1		*GARNISH RR BUMPER	Cut	141.00 FL	*141.00 FL
10	1		*SPACER R RR BUMPER SIDE	Necessary	35.00 FL	*35.00 FL
11	1		*SPACER L RR BUMPER SIDE	Not Necessary	35.00 FL	*- FL
12	1		*PANEL COMPRR	Dented	442.90 FL	*442.90 FL
13	1		*PANEL SET RR FLOOR	Not Necessary	731.40 FL	*- FL
14	1		*LINING ASSY RR PANEL	Deformed	60.80 FL	*60.80 FL
15	1		*PANEL REAR RH	Buckled	708.40 FL	*708.40 FL
16	1		*PANEL REAR RH VENT	Not Necessary	92.80 FL	*- FL
17	1		*REAR EXHAUST	Repair	568.90 FL	*-FL
F=Fra	nchise	part. L=ListIten	nDisc.			
				Sub Total (S\$)	5,290.90	3,411.60
			- List Item Discour	nt on L Items 20.00/20.00% (S\$)	1,058.18	682.32
				Total Parts (S\$)	4,232.72	2,729.28
			Report was unsubm	itted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	REMOVE & RENEW REVERSE SENSORS	New	120.00	50.00
2	SEALANT FOR REAR END PANEL	New	120.00	60.00
3	SEALANT FOR TAILGATE	New	120.00	60.00
4	INSPECT RR LIGHTING MECHANISMS ,PERFORM WATER	New	100.00	0.00
5	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	200.00	0.00
6	REMOVE & INSTALL RR WINDSCREEN	New	150.00	120.00
7	CUT OFF & RENEW RR PANEL	New	1,500.00	1,200.00
8	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,400.00	1,200.00
9	REMOVE,REFIX AND ALIGN REAR VIEW CAMERA	New	120.00	50.00
10	REMOVE & REFIT EXHAUST SYSTEM	New	150.00	60.00
	Gross L	abour Cost (S\$)	3,980.00	2,800.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >