3/10/23, 10:09 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III22006530/DVY3M4-1

10/03/2023 Date:

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01

**Claimant Vehicle** SLB8630B Insured Vehicle No: SLM4643H No:

Date of Loss: 14/05/2022 Nature of Claim: Claim No: MFL2022D0003625

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SLB8630B** 

TOYOTA COROLLA ALTIS, 1.6 L CVT (A) 1ZRX560144 Make & Model: Engine No:

Reg. Date: 25/04/2016 (Man. Year: 2015) Chassis No: MR053REH104547945

Colour: Brown Odometer: 309318 km

**Engine Capacity:** 1598 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 205/55 R16 Rear Tyre Size: Front Left Side: RAPID 6 mm Rear Left Side: RAPID 6 mm Front Right Side: RAPID 6 mm Rear Right Side: RAPID 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,312.18	1,464.64	1,847.54	55.78
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,050.00	1,090.00	960.00	46.83
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,362.18	2,554.64	2,807.54	52.36
	Approved Total (Overridden) (S\$)		2,050.00		
	Nett Amount (S\$)	5,362.18	2,050.00	3,312.18	61.77

**INSPECTION** 

Date of Assignment: 07/03/2023

AT PERFORMANCE

160 SIN MING DRIVE Date Inspected: 08/07/2022 Inspected At:

#07-18/19 SIN MING AUTOCITY

SINGAPORE 575722

Estimated Period of Repair: 4.0 days

Adjuster: **BRYAN TANI** Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Mar 2023)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB8630B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut/Damaged	891.24 F	*684.00 FL
2	2		*REAR BUMPER SIDE HOLDER	Affected	142.86 F	*142.86 FL
3	2		*REAR BUMPER SIDE RETAINER	Affected	188.40 F	*188.40 FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	627.40 F	*399.00 FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	149.08 F	*- FL
6	1		*SET REAR BUMPER CLIP	Necessary	28.00 F	*28.00 FL
7	2		*REAR BUMPER SENSOR	Malfunction	292.00 F	*292.00 FL
8	1		*REAR END PANEL	Repair	774.60 F	*- FL
9	1		*BOOTLID LOCK SENSOR	Damaged	178.60 F	*178.60 FL
10	1		*BOOTLID (NPA)	Repair	0.00 F	*- FL
11	1		*SUNDRIES	Necessary	40.00 FS	*30.00 FS
F=Fra	nchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	3,312.18	1,942.86
	- List Item Discount on L Items 0.00/25.00% (S\$)					478.22
				Total Parts (S\$)	3,312.18	1,464.64
			Report was unsubmitted	d during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	<u>our Items</u>			
1	TO REMOVE AND REPLACE DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS	New	750.00	400.00
2	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS. TO RESPRAY REPLACED AND OTHER AFFECTED PANELS	New	850.00	600.00
3	TO REMOVE AND REFIT BOOT COMPARTMENT FITTINGS & ATTACHMENTS TO FACILITATE REPAIR	New	150.00	0.00
4	TO CARRY OUT ANTI RUST TREATMENT	New	120.00	30.00
5	TO CHECK ELECTRICAL SYSTEMS FOR PROPER FUNCTIONS	New	100.00	30.00
6	TO INSTALL REAR BUMPER SENSOR	New	80.00	30.00
	Gross Labo	our Cost (S\$)	2,050.00	1,090.00
	Report was unsubmitted during thi	s print-out.		

< END OF ESTIMATES >