

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/TMI23002443/KNP3Q2**Date:** 27/03/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT000740	
Claimant Vehicle No :	SHB7822T	Insured Vehicle No :	SJE9888B	
Date of Loss:	18/02/2023	Nature of Claim:	TP	Claim No: M2301174

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7822T	Engine No:	2ZR2C52930
Make & Model:	TOYOTA PRIUS, 1.5 (A)	Chassis No:	JTDKB3FU103083452
Reg. Date:	30/08/2019 (Man. Year: 2018)	Odometer:	266964 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 8 mm	Rear Left Side:	Wanli 8 mm
Front Right Side:	Wanli 8 mm	Rear Right Side:	Wanli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,766.81	649.76	4,117.05	86.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,380.00	420.00	4,960.00	92.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,146.81	1,069.76	9,077.05	89.46
Approved Total (Overridden) (S\$)		850.00		
(S\$)	10,146.81	850.00	9,296.81	91.62
+ GST 8.00/8.00% (S\$)	811.74	68.00	743.74	91.62
Nett Amount (S\$)	10,958.55	918.00	10,040.55	91.62

INSPECTION

Date of Assignment:	17/03/2023		
Date Inspected:	07/03/2023	Inspected At:	Trans cab Auto Service - Ang Mo Kio (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2023)
Parts:	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB7822T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Repair	558.39 FL	*- FL
2	1		*COVER ,REAR BUMPER LOWER	Dented	19.43 FL	*19.43 FL
3	1		*GUARD ,REAR BUMPER CENTER	Dented / Cut	726.92 FL	*726.92 FL
4	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Serviceable	155.72 FL	*- FL
5	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	419.90 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	147.11 FL	*- FL
7	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	148.58 FL	*- FL
8	1		*COVER ,FLOOR UNDER NO.2 (RH)	Serviceable	220.50 FL	*- FL
9	1		*COVER ,FLOOR UNDER NO.2 (LH)	Serviceable	304.92 FL	*- FL
10	1		*COVER ,REAR FLOOR (CTR)	Serviceable	290.43 FL	*- FL
11	1		*COVER ,DECK TRIM ,REAR	Serviceable	159.39 FL	*- FL
12	1		*PANEL SUB-ASSY BODY LOWER BACK	Repair	824.46 FL	*- FL
13	1		*PARKING AID	Serviceable	700.00 FS	*- FS
14	1		*REAR LOWER BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
15	1		*REAR BUMPER CLIP	Not Necessary	60.00 FS	*- FS
16	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
17	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
18	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
19	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
20	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
21	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	*30.00 FS
22	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	140.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,760.75	836.35
- List Item Discount on L Items 25.00/25.00% (\$\$)	993.94	186.59
Total Parts (\$\$)	4,766.81	649.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,400.00	200.00
3	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	220.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
6	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
7	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
8	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
9	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross Labour Cost (S\$)			5,380.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >