

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23002445/AQP3E2**Date:** 03/08/2023**REFERENCE**

Insured/Claimant:	LIM TEO WENG	Policy No:	7210110869	
Date of Loss:	01/03/2023	Nature of Claim:	OD	Claim No: 4244392132SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB7686Z		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC48819
Reg. Date:	14/09/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF35M1152923
Colour:	White	Odometer:	27418 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R19	Rear Tyre Size:	235/50 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,253.00	3,053.36	1,199.64	28.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,392.00	1,822.00	1,570.00	46.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,645.00	4,875.36	2,769.64	36.23
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	6,845.00	4,075.36	2,769.64	40.46
+ GST 8.00/8.00% (\$\$)	547.60	326.03	221.57	40.46
Nett Amount (\$\$)	7,392.60	4,401.39	2,991.21	40.46

INSPECTION

Date of Assignment:	08/03/2023		
Date Inspected:	06/03/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Dented	3,203.00 FS	*2,562.40 FS
2	1		*FRONT DOOR OUTER SEAL - RH	Necessary	196.00 FS	*156.40 FS
3	1		*FRONT DOOR CATCH - RH	Not Necessary	141.00 FS	*- FS
4	1		*FRONT DOOR COVER - RH	Necessary	413.00 FS	*330.40 FS
5	1		*SUNDRIES	Necessary	300.00 FS	*4.16 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					4,253.00	3,053.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
2	TO DISMANTLE AND RENEW RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY RHS FRONT DOOR AND DOOR COVER	New	1,600.00	850.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,392.00	1,822.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >