

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23002446/SWY3M4**Date:** 10/05/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR005820		
Claimant Vehicle No :	SHC153G	Insured Vehicle No :	SKK2007E		
Date of Loss:	05/03/2023	Nature of Claim:	TP	Claim No:	M2301570

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC153G	Engine No:	G4LEKU297721
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU164638
Reg. Date:	02/07/2019 (Man. Year: 2019)	Odometer:	318514 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	979.28	946.12	33.16	3.39
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	820.00	630.00	190.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,810.28	1,587.12	223.16	12.33
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	1,810.28	1,250.00	560.28	30.95
+ GST 8.00/8.00% (S\$)	144.82	100.00	44.82	30.95
Nett Amount (S\$)	1,955.10	1,350.00	605.10	30.95

INSPECTION

Date of Assignment:	08/03/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969
Date Inspected:	08/03/2023	Inspected At:	
Estimated Period of Repair:	2.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 May 2023)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC153G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	Scratched	451.25 FL	*451.25 FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR BUMPER REFLECTOR RH	Not Necessary	41.45 FL	*- FL
5	2		*REAR FENDER ADV.STICKER RH / LH	Necessary	200.00 F	*200.00 F
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	1,174.10
					- List Item Discount on L Items 20.00/20.00% (S\$)	194.82
					Total Parts (S\$)	979.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	R/I REVERSE SENSORS	New	120.00	30.00
Gross Labour Cost (\$\$)			820.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >