4/25/23, 9:30 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI23002457/RVY3Q2

25/04/2023 Date:

**REFERENCE** 

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle** SBD8508E Insured Vehicle No:

SMU1656L No:

Date of Loss: 05/03/2023 Nature of Claim: TP Claim No: CDMPG23000554

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SBD8508E** 

ADIVA AD1 200, 190cc 3W 3A92UHX7366 Make & Model: Engine No:

Reg. Date: 06/12/2019 (Man. Year: 2019) Chassis No: MMBSTA13AKH002589

Colour: Odometer: 2657 km Grey

**Engine Capacity:** 1193 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 185/55 R15 185/55 R15 Rear Tyre Size: Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,967.30	1,700.00	1,267.30	42.71
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,590.00	840.00	750.00	47.17
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,557.30	2,540.00	2,017.30	44.27
	Approved Total (Overridden) (S\$)		2,000.00		
	(S\$)	4,557.30	2,000.00	2,557.30	56.11
	+ GST 8.00/8.00% (S\$)	364.58	160.00	204.58	56.11
	Nett Amount (S\$)	4,921.88	2,160.00	2,761.88	56.11

**INSPECTION** 

Date of Assignment: 08/03/2023

Wah Hong Motors & Credit Pte Ltd (HQ) Date Inspected: 04/04/2023 Inspected At:

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/25/23, 9:30 AM Adjuster Report

## **REPAIR DETAILS**

### Reference

Part Source: (Last Synchronised: 24 Apr 2023)

Parts: N/A ADIVA AD1 200 190cc 3W (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBD8508E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID LOGO BADGE	Necessary	41.00 FL	*41.00 FL
2	1		*BOOT LID EMBLEM ATTRAGE	Necessary	38.00 FL	*38.00 FL
3	1		*BOOT LID EMBLEM MIVEC	Necessary	85.00 FL	*85.00 FL
4	1		*TAIL LAMP RH	Not Necessary	276.00 FL	*- FL
5	1		*REAR BUMPER	Deformed	708.00 FL	*708.00 FL
6	1		*REAR BUMPER SIDE RETAINER RH/LH	O/S Necessary	56.00 FL	*28.00 FL
7	1		*REAR BUMPER LOWER SKIRT	Cracked	1,478.70 FS	*800.00 FS
8	1		*BOOT LID (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*END PANEL (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*REAR FENDER RH (NPA)	Not Necessary	0.00 FL	*- FL
11	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
12	1		*REAR REVERSE SENSOR	Not Necessary	200.00 FS	*- FS
13	1		*BOOT LID EMBLEM CC	Necessary	100.00 FS	*30.00 FS
14	1		*REAR BUMPER LOWER SKIRT CLIPS	Necessary	35.00 FS	*30.00 FS
15	1		*REAR CAR PLATE WITH HOLDER	Not Necessary	35.00 FS	*- FS
F=Fra	ınchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	3,087.70	1,790.00
			- List Item Discount on	L Items 10.00/10.00% (S\$)	120.40	90.00
				Total Parts (S\$)	2,967.30	1,700.00
			Report was unsubmitted du	ring this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	600.00	300.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	800.00	500.00
3	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	90.00	0.00
4	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	100.00	40.00
	Gross Labou	ır Cost (S\$)	1,590.00	840.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >