

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG123002461/RNY3Q2**Date:** 20/04/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** SNA7281M **Insured Vehicle No :** SNJ791G

Date of Loss: 06/03/2023 Nature of Claim: TP Claim No: CDMPG23000556-002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA7281M**

Make & Model: SKODA SCALA, 1.5 AMBITION TSI (A) Engine No: DPC191028

Reg. Date: 09/07/2021 (Man. Year: 2021) Chassis No: TMBFK6NW0M3126688

Colour: White Odometer: 34694 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45 R18 Rear Tyre Size: 205/45 R18

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 5,122.42          | 2,282.74          | 2,839.68          | 55.44         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 9,800.00          | 2,800.00          | 7,000.00          | 71.43         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>14,922.42</b>  | <b>5,082.74</b>   | <b>9,839.68</b>   | <b>65.94</b>  |
| <b>+ GST 8.00/8.00% (S\$)</b> | <b>1,193.79</b>   | <b>406.62</b>     | <b>787.17</b>     | <b>65.94</b>  |
| <b>Nett Amount (S\$)</b>      | <b>16,116.21</b>  | <b>5,489.36</b>   | <b>10,626.85</b>  | <b>65.94</b>  |

INSPECTION

Date of Assignment: 08/03/2023

Date Inspected: 10/03/2023 Inspected At: Volkswagen Group Singapore Pte Ltd  
247 ALEXANDRA ROAD  
Singapore 159934

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                    |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 19 Apr 2023)                                                                                                                                             |                                                                    |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | SKODA SCALA 1.5 AMBITION TSI (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SNA7281M)                                                                                                                                    |                                                                    |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                    |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                    |

### Recommended Parts

| No. | Qty | Part No. Particulars                                  | Condition     | Repairer's  | Amount       |
|-----|-----|-------------------------------------------------------|---------------|-------------|--------------|
| 1   | 1   | *UNBEKANNT BOOT LID NAME PLATE -SCALA                 | Not Necessary | 95.63 FS    | *- FS        |
| 2   | 1   | *STOBFANGE RREAR BUMPER                               | Deformed      | 1,656.46 FS | *1,656.46 FS |
| 3   | 1   | *GEBERHALTER SENSOR BRACKET                           | Necessary     | 14.14 FS    | *14.14 FS    |
| 4   | 1   | *GEBERHALTER                                          | Necessary     | 14.14 FS    | *14.14 FS    |
| 5   | 1   | *GEBERHALTER                                          | Necessary     | 14.14 FS    | *14.14 FS    |
| 6   | 1   | *GEBERHALTER                                          | Necessary     | 14.14 FS    | *14.14 FS    |
| 7   | 1   | *SENSOR PRIMED                                        | Not Necessary | 194.63 FS   | *- FS        |
| 8   | 1   | *SEAL RING SATIN BLACK                                | Necessary     | 1.53 FS     | *1.53 FS     |
| 9   | 1   | *2K-PLASTIC ADHESIVE                                  | Necessary     | 84.64 FS    | *84.64 FS    |
| 10  | 1   | *BONDING AGENT FOR PLASTIC                            | Necessary     | 74.37 FS    | *74.37 FS    |
| 11  | 1   | *UNBEKANNT BUMPER SPOILER                             | Scratched     | 260.15 FS   | *260.15 FS   |
| 12  | 1   | *SCHAUMSTOFFROHR REINFORCEMENT                        | Not Necessary | 118.39 FS   | *- FS        |
| 13  | 1   | *UNBEKANNT BUMPER CTR BRACKET                         | Not Necessary | 72.05 FS    | *- FS        |
| 14  | 1   | *RHS GUIDE PROFILE RHR BUMPER BRACKET (UPPER)         | Not Necessary | 41.04 FS    | *- FS        |
| 15  | 1   | *LHS GUIDE PROFILE LHR BUMPER BRACKET (UPPER)         | Not Necessary | 41.04 FS    | *- FS        |
| 16  | 1   | *LHS GUIDE PROFILE LHR BUMPER BRACKET (SIDE)          | Not Necessary | 52.45 FS    | *- FS        |
| 17  | 1   | *RHS GUIDE PROFILE RHR BUMPER BRACKET (SIDE)          | Not Necessary | 49.54 FS    | *- FS        |
| 18  | 1   | *LED-SCHLUSSLEUCHTE LHR TAILLIGHT OUTER               | Not Necessary | 898.49 FS   | *- FS        |
| 19  | 1   | *RUCKSTRAHLER LHS REFLECTOR                           | Cracked       | 49.03 FS    | *49.03 FS    |
| 20  | 1   | *CONTROL UNIT FOR BLIND SP BLIND SPOT CONTROL UNIT LH | Not Necessary | 1,033.22 FS | *- FS        |
| 21  | 1   | *HALTER BLIND SPOT CONTROL UNIT BRACKET LH            | Not Necessary | 19.51 FS    | *- FS        |
| 22  | 1   | *WHEELHOUSE LHR FENDER LINER                          | Not Necessary | 223.69 FS   | *- FS        |
| 23  | 1   | *COATING                                              | Necessary     | 100.00 FS   | *100.00 FS   |

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 5,122.42 2,282.74**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                       | Particulars                            | Lab.Type | Repairer's | Amount   |
|--------------------------|----------------------------------------|----------|------------|----------|
| <b>Labour Items</b>      |                                        |          |            |          |
| 1                        | LABOUR                                 | New      | 4,200.00   | 840.00   |
| 2                        | SPRAY PAINT                            | New      | 4,000.00   | 1,200.00 |
| 3                        | B&P CHECK SHORT CIRCUIT/HARNESS REPAIR | New      | 280.00     | 280.00   |
| 4                        | B&P DIAGNOSIS AND PROGRAMMING          | New      | 480.00     | 480.00   |
| 5                        | CHARGE LANE ASSIST SYSTEM CALIBRATION  | New      | 840.00     | 0.00     |
| Gross Labour Cost (\$\$) |                                        |          | 9,800.00   | 2,800.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >