

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI23002462/RVP3Q2**Date:** 03/07/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00249082200

**Claimant Vehicle No :** SMY3398Y **Insured Vehicle No :** SMV7677G

Date of Loss: 06/03/2023 Nature of Claim: TP Claim No: SNM23D201749/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMY3398Y**

Make & Model: BMW 520i, 2.0 LUXURY ADAP LED HL (A) Engine No: 24176273B48B20A

Reg. Date: 09/02/2021 (Man. Year: 2020) Chassis No: WBA72AG090WX07919

Colour: Black Odometer: 37510 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 245/40 R19 Rear Tyre Size: 245/40 R19

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,025.65	3,233.10	1,792.55	35.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,555.00	4,008.00	547.00	12.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,580.65</b>	<b>7,241.10</b>	<b>2,339.55</b>	<b>24.42</b>
<b>+ GST 8.00/8.00% (S\$)</b>	766.45	579.29	187.16	24.42
<b>Nett Amount (S\$)</b>	<b>10,347.10</b>	<b>7,820.39</b>	<b>2,526.71</b>	<b>24.42</b>

**INSPECTION**

Date of Assignment: 08/03/2023

Date Inspected: 21/03/2023 Inspected At: Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance Centre  
Singapore 159941

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jul 2023)
Parts:	143	BMW 520I 2.0 LUXURY ADAP LED HL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY3398Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*LEFT PROTECTION FOIL	Not Necessary	14.15 FS	*- FS
3	1		*RIGHT PROTEC	Not Necessary	14.15 FS	*- FS
4	1		*REAR BUMPER CARRIER	Bent	608.95 FS	*608.95 FS
5	1		*REAR BUMPER TRIM STRIP (LUXURY)	Cut	159.60 FS	*159.60 FS
6	1		*REAR BUMPER BOTTOM TRIM PANEL	Scratched	317.05 FS	*317.05 FS
7	1		*REAR CENTRE GUIDE	Cracked	179.90 FS	*179.90 FS
8	1		*REAR BUMPER BOTTOM REINFORCEMENT	Bent	171.90 FS	*171.90 FS
9	1		*REAR TOWING EYE COVER PRIMED	Not Necessary	55.30 FS	*- FS
10	1		*REAR BUMPER TRIM PANEL (PDC/PMA)	Deformed	1,664.50 FS	*1,664.50 FS
11	1		*SET MOUNTING PDA/PMA SENSOR REAR	Not Necessary	73.75 FS	*- FS
12	4		*DECOUPLING RING	Not Necessary	21.20 FS	*- FS
13	4		*ULTRASONIC SENSOR SOPHISTO GREY	Not Necessary	1,544.00 FS	*- FS
14	1		*UNDERBODY PANELLING REAR	Cracked	51.20 FS	*51.20 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	5,025.65 3,233.10

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER PANEL ,REAR UNDERBODY PANELLING ,REAR BOTTOM REINFORCEMENT ,REAR CENTRE GUIDE ,REAR BOTTOM TRIM PANEL ,REAR TRIM STRIP,REAR CARRIER INCLUDE MAKING GOOD THE BOOT LID AND CARRYING OUT NECESSARY REPAIRS CAUSED BY THE ACCIDENT	New	2,125.00	1,700.00
2	PAINTING REAR BUMPER AND REAR BOOT LID	New	2,076.00	1,972.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
<b>Gross Labour Cost (S\$)</b>			<b>4,555.00</b>	<b>4,008.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >