

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III23002469/UVY3Q2**Date:** 23/03/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No:
Claimant Vehicle No : SKN8080L **Insured Vehicle No :** SLS9256C
 Date of Loss: 06/03/2023 Nature of Claim: TP Claim No: D21MFL0000447_02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKN8080L**
 Make & Model: ADIVA AD1 200, 190cc 3W Engine No: 64286141517111
 Reg. Date: 11/08/2014 (Man. Year: 2014) Chassis No: WDD2221322A028958
 Colour: Grey/Silver Odometer: 103653 km
 Engine Capacity: 2987 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R19 Rear Tyre Size: 275/40 R19
 Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 7 mm
 Front Right Side: Goodyear 7 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,424.45	650.00	4,774.45	88.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	390.00	310.00	44.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	6,124.45	1,040.00	5,084.45	83.02

INSPECTION

Date of Assignment: 08/03/2023
 Date Inspected: 10/03/2023 Inspected At: EEVolveauto Workshop LLP (HQ)
 1 Kaki Bukit Avenue 6, #02-25 Autobay @ Kakit
 Bukit
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Mar 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKN8080L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	3,678.90 FL	*- FL
2	1		*FRONT FENDER SIDE RETAINER RH	Not Necessary	95.60 FL	*- FL
3	1		*FRONT BUMPER INNER BRACKET RH	Not Necessary	268.90 FL	*- FL
4	1		*ENERGIZER SPONGE	Not Necessary	214.50 FL	*- FL
5	1		*FOGLIGHT COVER RH	Not Necessary	145.60 FL	*- FL
6	1		*FOGLIGHT CHROME RH	Not Necessary	213.60 FL	*- FL
7	1		*FOGLIGHT HOLDER SUPPORT RH	Not Necessary	123.40 FL	*- FL
8	10		*SET BUMPER CLIP	Not Necessary	50.00 FS	*- FS
9	8		*BUMPER RIVET	Not Necessary	56.00 FS	*- FS
10	2		*PARKTRONIC PARKING SENSOR	Serviceable	350.00 FS	*- FS
11	1		*TO REWRAP 3M STICKER	Necessary	702.00 FS	*650.00 FS
					Sub Total (\$\$)	5,898.50 650.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	474.05 0.00
					Total Parts (\$\$)	5,424.45 650.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE ,REPAIR AND REPLACE	New	300.00	100.00
2	SPRAY PAINTING	New	300.00	250.00
3	TO TRANSFER AND CHECK WIRING	New	100.00	40.00
Gross Labour Cost (S\$)			700.00	390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >