

ASS. REC. BY:

REF:

AIG/230024761ky

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s

Trans Cab

of

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SHD 9612J

Yr Regn: _____

06, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: _____

Toy Prius

c.c

1798

Colour

M.P. White / R

A/C:

Insured / Std / NI / NA

Sp. Reading

222922

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JTD KB3FU 703081740

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size: _____

F: Wanh

195/65R15

R: Navigator

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

8

mm

Rear

R/Bal. _____

6

mm

L/Bal. _____

8

mm

L/Bal. _____

6

mm

D.O.A. _____

24/2/23

D.O.I. _____

6/3/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/3 21h @ 1250h Cab

Date/Time, File Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

1)

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

: Fuel

: Others

TOTAL

Not Authorised
C/Pay 81250h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD9612J

AAD2302-

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

06 MAR 2023

SHD9612J

JTDKB3FU703081740

200303878K

TOYOTA

PRIUS

24/02/2023

SLX8707Z/

27/06/2019

PART	LIST
1 COVER, REAR BUMPER	\$ Bu 558.39 —
1 COVER, REAR BUMPER, LOWER	\$ Lu 19.43 X
1 GUARD, REAR BUMPER, CENTER	\$ nu 726.92 —
SEAL, REAR BUMPER SIDE, LH	\$ Lu 111.41 X
1 SEAL, REAR BUMPER SIDE, RH	\$ Lu 111.41 X
RETAINER, REAR BUMPER SIDE, LH	\$ Lu 147.11 X
1 REAR BUMPER SIDE RETAINER RH	\$ Lu 148.58 X
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ R 419.90 X
1 COVER, FLOOR UNDER, RH	\$ Lu 220.50 X
1 COVER, FLOOR UNDER, LH	\$ Lu 304.92 X
1 COVER, REAR FLOOR	\$ Lu 290.43 X
1 COVER, BACK DOOR TRIM	\$ Lu 31.50 X
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ R 824.46 X
1 PANEL SUB-ASSY, BACK DOOR	\$ R 1,443.86 X
1 STAY ASSY, BACK DOOR, LH	\$ Lu 305.66 X
1 STAY ASSY, BACK DOOR, RH	\$ Lu 305.66 X
1 HINGE ASSY, BACK DOOR, LH	\$ R 77.18 X
1 HINGE ASSY, BACK DOOR, RH	\$ R 77.18 X
1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ Lu 1,171.38 X
1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$ nu 68.88 X
1 PLATE, BACK DOOR NAME, NO.1	\$ nu 68.88 X
1 ORNAMENT SUB-ASSY, BACK DOOR	\$ nu 90.30 X
TOTAL	\$ 3,914.93
25%	\$ 978.73
	\$ 2,936.20

SPECIAL NETT

1SET PARKING AID

1 REAR BUMPER CLIP

\$ Lu 700.00 X
\$ nu 65.00 65.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

AAD2302-**SHD9612J**

- 1 FENDER LINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER ADVERTISEMENT
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	na	65.00	X
\$	na	65.00	X
\$	na	65.00	X
\$	na	60.00	X
\$	na	100.00	60.00
\$	na	180.00	X
\$	na	150.00	X
\$	na	200.00	X
\$	na	130.00	X
TOTAL		\$ 1,780.00	
TOTAL PARTS		\$ 4,716.20	

LABOUR

To rust-proofing of the affected areas.	\$	na	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	2201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	2001
To transfer of tailgate fittings and conduct water seepage test.	\$	na	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4	380.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	4	170.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	4	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	4	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	501

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD9612J

AAD2302-

To check steering geometry and computer wheel alignment \$ *na* 220.00 X

To Transfer Of Fender Fittings, Attachments And Perform
Water Seepage Test.

\$ *na* 170.00 X

TOTAL \$ 5,420.00

OVERALL TOTAL \$ 10,136.20

2 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

