

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG23002479/APA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220064918
<b>Claimant Vehicle No :</b>	PC5353T	<b>Insured Vehicle No :</b>	SNF1027U
Date of Loss:	17/02/2023	Nature of Claim:	TP
		Claim No:	6218514642SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>PC5353T</b>	Engine No:	6HK1663499
Make & Model:	ISUZU LT434P 7.8 SMT, 7.8 D (M)	Chassis No:	JALLT434PE7000088
Reg. Date:	15/01/2015 (Man. Year: 2014)	Odometer:	290149 km
Colour:	Grey		
Engine Capacity:	7790 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Runever 6 mm	Rear Left Side:	Runever 6 mm
Front Right Side:	Runever 6 mm	Rear Right Side:	Runever 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,260.00	1,500.00	5,760.00	79.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	870.00	2,710.00	75.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,840.00</b>	<b>2,370.00</b>	<b>8,470.00</b>	<b>78.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,840.00</b>	<b>1,900.00</b>	<b>8,940.00</b>	<b>82.47</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment:	21/02/2023		
Date Inspected:	21/02/2023	Inspected At:	YSK Auto Workshop (HQ) 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71 Singapore 417883
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,800.00 FS	*1,500.00 FS
2	2		*FRONT BUMPER HOLDER	Not Necessary	200.00 FS	*- FS
3	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	280.00 FS	*- FS
4	1		*FRONT BUMPER FOG LAMP COVER LH	Not Necessary	150.00 FS	*- FS
5	1		*FRONT BODY PANEL	Repair	3,000.00 FS	*- FS
6	1		*FRONT WINDSCREEN MOULDING	Not Necessary	550.00 FS	*- FS
7	1		*FRONT WINDSCREEN SEALANT	Not Necessary	280.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					<b>Total Parts (\$)</b>	<b>7,260.00 1,500.00</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,500.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	400.00
3	WIRING CHECK	New	100.00	30.00
4	TO APPLY TUFF COAT	New	180.00	40.00
5	TO REMOVE FRONT WINDSCREEN	New	600.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,580.00</b>	<b>870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >