

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : PC5353T
VEHICLE MODEL : ISUZU LT434P
CHASSIS NO : JALLT434PE7000088

TP A16

Xiao Tony

CLAIM DETAILS: PARTS

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Debond</i>	1	\$ 2,800.00	\$ 2,800.00
2	FRONT BUMPER HOLDER <i>new</i>	2	\$ 100.00	\$ 200.00
3	FRONT BUMPER FOG LAMP LH <i>new</i>	1	\$ 280.00	\$ 280.00
4	FRONT BUMPER FOG LAMP COVER LH <i>new</i>	1	\$ 150.00	\$ 150.00
5	FRONT BODY PANEL <i>repair</i>	1	\$ 3,000.00	\$ 3,000.00
6	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 550.00	\$ 550.00
7	FRONT WINDSCREEN SEALANT <i>new</i>	1	\$ 280.00	\$ 280.00
TOTAL :				\$ 7,260.00

1500

1500

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,500.00	<i>400</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>400</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 180.00	<i>40</i>	
5	TO REMOVE FRONT WINDSCREEN	\$ 600.00	<i>x</i>	
TOTAL:		\$ 3,580.00		

870

ESTIMATE REPORT

TOTAL PARTS COST: \$ 7,260.00
TOTAL LABOUR COST: \$ 3,580.00
TOTAL REPAIR COST: \$ 10,840.00

total 2370

4/5 : 1.9K

03 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FAX:

Acknowledged by Repairer

Signature:

Date: