

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAI	NCE BHD	Ref:	CS3/LPC23002481/Wqy3m4	
	300 BEACH ROAD #17-04/07 THE CC	) NCOURSESINGAPORE 199555	Date	e: 14/03/2023	
			Cod	e: LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBF 9720R	Veh. Inspected	SLE 8875X	
	Policy No.	Z22VC05011324	Coverage (\$)	0.00	
	Claim No.	22/23/23/VC05/027076	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	07/03/2023	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	RU11112739	Colour	WHITE	
	Odometer	108152 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	TOYO	7 mm	
	L/H Front Tyre	215/55 R17	TOYO	7 mm	
	R/H Rear Tyre	215/55 R17	TOYO	7 mm	
	L/H Rear Tyre	215/55 R17	TOYO	7 mm	
4.	Description of Damages				
	THE VEHICLE SU	STAINED DAMAGES AT THE RE			
5.	General Information				
	Accident Date	06/03/2023	Inspect Date / Time	9 08/03/2023 ( 10:50 AM )	
	Survey held at	KARR AUTOWORKS PTE LTD			
		BLK 8 KAKI BUKIT AVE 4 #02-24 SINGAPORE 415875			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC23002481/Wqy3m4

Inspected By

MUHAMMAD AKID BIN MOHAMED KAMAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser