

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002489/AVY3E2
Date: 28/04/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00033312200
Claimant Vehicle No :	SLR1208A	Insured Vehicle No :	GBL7363U
Date of Loss:	01/03/2023	Nature of Claim:	TP
		Claim No:	SNM23D201791/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR1208A	Engine No:	LEB5535337
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71012675
Reg. Date:	31/07/2017 (Man. Year: 2016)	Odometer:	85522 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,072.00	1,052.00	20.00	1.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,000.00	680.00	40.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,752.00	2,052.00	700.00	25.44
+ GST 8.00/8.00% (S\$)	220.16	164.16	56.00	25.44
Nett Amount (S\$)	2,972.16	2,216.16	756.00	25.44

INSPECTION

Date of Assignment:	09/03/2023	
Date Inspected:	15/03/2023	Inspected At: BW Workshop Services Pte Ltd (HQ) 291 Kaki Bukit Avenue 1, Shun Li Industrial Park Singapore 416080
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2023)
Parts: M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR1208A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR TAILGATE	Dented	1,240.00 FL	*1,240.00 FL	
2	1		*REAR BUMPER (NPA)	Repair	0.00 FL	*- FL	
3	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS	
					Sub Total (\$)	1,320.00	1,300.00
					- List Item Discount on L Items 20.00/20.00% (\$)	248.00	248.00
					Total Parts (\$)	1,072.00	1,052.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS	New	800.00	400.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	400.00	350.00
3	TO TRANSFER TAILGATES FITTINGS	New	150.00	80.00
4	TO REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
5	TO REMOVE AND REFIT REVERSE CAMERA	New	120.00	50.00
6	TO APPLY RUST PROOFING ON THE ADJUSTMENT PANELS	New	60.00	0.00
Gross Labour Cost (\$\$)			1,680.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >