

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002497/RNY3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00007872207

Claimant Vehicle No : SKX622Z **Insured Vehicle No :** CB6349J

Date of Loss: 07/03/2023 Nature of Claim: TP Claim No: SNM23D201775/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX622Z**

Make & Model: HONDA ODYSSEY, 2.3 (A) Engine No: K24W72402071

Reg. Date: 10/08/2018 (Man. Year: 2018) Chassis No: JHMRC1890JC204671

Colour: Maroon Odometer: 91329 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,742.18	1,687.62	6,054.56	78.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,030.00	6,875.00	8,155.00	54.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,772.18	8,562.62	14,209.56	62.40
+ GST 8.00/8.00% (S\$)	1,821.77	685.01	1,136.76	62.40
Nett Amount (S\$)	24,593.95	9,247.63	15,346.32	62.40

INSPECTION

Date of Assignment: 09/03/2023

Date Inspected: 20/03/2023 Inspected At: Kah Motor Co Sdn Bhd (ALEXANDRA)
255 ALEXANDRA ROAD
Singapore -

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2023)
Parts:	M1-MPV	HONDA ODYSSEY 2.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX622Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	110.00 FS	*30.00 FS
2	4		*REAR SENSORS	Not Necessary	320.00 FS	*- FS
3	1		*NUMBER PLATE WITH CASING -L	Not Necessary	45.00 FS	*- FS
4	1		*TAILLIGHT ASSYR	Not Necessary	672.90 FS	*- FS
5	1		*TAILLIGHT ASSYL	Not Necessary	672.90 FS	*- FS
6	1		*LIGHT ASSY ,R.LID	Not Necessary	310.05 FS	*- FS
7	1		*LIGHT ASSYL.LID	Not Necessary	310.05 FS	*- FS
8	1		*GARNISH ASSYRR.LICENSE	Not Necessary	185.02 FS	*- FS
9	1		*TAILGATE COMP	Bent	859.65 FS	*859.65 FS
10	1		*WEATHERSTRIPTAILGATE	Not Necessary	94.27 FS	*- FS
11	1		*MOLDING ASSYRR.LICENSE GARN	Not Necessary	140.92 FS	*- FS
12	1		*GARNISH ASSYTAILGATE SPOILER	Not Necessary	508.05 FS	*- FS
13	6		*CLIPTAILGATE SPOILER	Necessary	11.70 FS	*11.70 FS
14	1		*EMBLEMH	Necessary	21.15 FS	*21.15 FS
15	1		*FACERRBUMPER	Deformed	456.22 FS	*421.50 FS
16	1		*REFLECTOR ASSYR.RR	Not Necessary	36.37 FS	*- FS
17	1		*REFLECTOR ASSYL.RR	Not Necessary	36.37 FS	*- FS
18	1		*FACER.RR.BUMPER GARNISH	Not Necessary	63.52 FS	*- FS
19	1		*FACEL.RR.BUMPER GARNISH	Not Necessary	63.52 FS	*- FS
20	1		*SPOILER ASSY,R.RR.SIDE	Not Necessary	94.35 FS	*- FS
21	1		*SPOILER ASSY,L.RR.SIDE	Not Necessary	94.35 FS	*- FS
22	1		*SPACERR.RR.BUMPER SIDE	Necessary	15.30 FS	*15.30 FS
23	1		*SPACERL.RR.BUMPER SIDE	Necessary	15.30 FS	*15.30 FS
24	1		*CLIP BUMPER (7 PCS)	Necessary	12.07 FS	*12.07 FS
25	1		*PANEL COMP,RR	Repair	369.90 FS	*- FS
26	1		*PAN SET3RD SEAT	Not Necessary	279.45 FS	*- FS
27	3		*OILSHEET	Not Necessary	97.87 FS	*- FS
28	1		*LINING ASSYTAILGATE LOWER	Not Necessary	165.60 FS	*- FS
29	1		*POCKETTAILGATE LINING PULL	Not Necessary	8.62 FS	*- FS
30	1		*LINING COMPR RR.SIDE	Not Necessary	606.90 FS	*- FS
31	1		*LINING ASSYRR PANEL	Not Necessary	83.17 FS	*- FS
32	1		*COMP LIDTOOL	Not Necessary	49.27 FS	*- FS
33	1		*LINING COMPL.RR.SIDE	Not Necessary	631.42 FS	*- FS
34	2		*MOLDINGRR.WINDSHIELD SIDE	Necessary	28.80 FS	*28.80 FS
35	1		*MOLDINGR.RR.WINDSHIELD CORNER	Missing	13.57 FS	*13.57 FS
36	1		*MOLDINGL.RR.WINDSHIELD CORNER	Missing	13.57 FS	*13.57 FS
37	4		*SPACERRR.W/SHIELD	Necessary	12.60 FS	*12.60 FS
38	1		*RUBBER AWINDSHIELD DAM	Necessary	2.92 FS	*2.92 FS
39	1		*DAMPERSTD 5X5 (2 PCS)	Necessary	13.65 FS	*13.65 FS
40	1		*CAPPIVOT	Necessary	3.90 FS	*3.90 FS
41	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
42	1		*EMBLEM RR	Necessary	24.90 FS	*24.90 FS
43	1		*RETAINER PARKING	Necessary	33.52 FS	*33.52 FS
44	1		*RETAINER ,PARKING D	Missing	33.52 FS	*33.52 FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					7,742.18	1,687.62
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & RENEW REVERSE SENSORS	New	250.00	180.00
2	SEALANT FOR REAR END PANEL	New	120.00	0.00
3	SEALANT FOR TAILGATE	New	120.00	100.00
4	SEALANT FOR REAR FLOOR PANEL	New	120.00	0.00
5	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	250.00	180.00
6	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	650.00	0.00
7	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	650.00	325.00
8	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	650.00	650.00
9	REMOVE & INSTALL RR WINDSCREEN	New	650.00	650.00
10	WINDSCREEN DAMKIT	New	120.00	120.00
11	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	650.00	0.00
12	CUT OFF & RENEW RR PANEL	New	5,000.00	1,950.00
13	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,500.00	1,560.00
14	REMOVE & RENEW RR FLOOR INSULATOR	New	480.00	0.00
15	RESET AND CALIBRATE ALL SMART ENTRY	New	650.00	580.00
16	REMOVE REFIX AND ALIGN REAR VIEW CAMERA	New	650.00	580.00
17	APPLY BODY UNDERSIDE COATING	New	520.00	0.00
Gross Labour Cost (S\$)			15,030.00	6,875.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >