

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS23002502/SQY3Q2**Date:** 14/07/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SLV7336C **Insured Vehicle No :** YR38B

Date of Loss: 05/03/2023 Nature of Claim: TP Claim No: DMCV2300016H/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV7336C**

Make & Model: HONDA SHUTTLE, 1.5 (A) Engine No: L15B5460362

Reg. Date: 12/01/2018 (Man. Year: 2017) Chassis No: GK81200297

Colour: White Odometer: 75507 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,722.07	4,812.18	1,909.89	28.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,540.00	640.00	29.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,902.07</b>	<b>6,352.18</b>	<b>2,549.89</b>	<b>28.64</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>712.17</b>	<b>508.17</b>	<b>204.00</b>	<b>28.64</b>
<b>Nett Amount (S\$)</b>	<b>9,614.24</b>	<b>6,860.35</b>	<b>2,753.89</b>	<b>28.64</b>

INSPECTION

Date of Assignment: 08/03/2023

Date Inspected: 09/03/2023 Inspected At: AUTO INSURE PTE LTD (HQ)  
6 MARSILING LANE  
Singapore 739145

Estimated Period of Repair: 5.0 days

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 13 Jul 2023)	
<b>Parts:</b>	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV7336C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,431.84 FL	*1,193.00 FL
2	1		*TAILGATE WEATHERSTRIP	Crumpled	161.89 FL	*161.89 FL
3	1		*TAILGATE WINDSCREEN	Broken	1,201.84 FL	*1,201.84 FL
4	1		*TAILGATE ABSORBER LH	Not Necessary	131.96 FL	*- FL
5	1		*TAILGATE ABSORBER RH	Not Necessary	131.96 FL	*- FL
6	1		*TAILGATE HINGE LH	Not Necessary	68.24 FL	*- FL
7	1		*TAILGATE HINGE RH	Not Necessary	68.24 FL	*- FL
8	1		*TAILGATE LOGO (H)	Necessary	65.84 FL	*65.84 FL
9	1		*TAILGATE EMBLEM (SHUTTLE)	Necessary	95.04 FL	*95.04 FL
10	1		*TAILGATE GARNISH (CHROME)	Not Necessary	459.72 FL	*- FL
11	1		*TAILGATE LOCK	Scratched	215.92 FL	*215.92 FL
12	1		*TAILGATE LAMP LH	Cracked	574.48 FL	*495.00 FL
13	1		*TAILGATE LAMP RH	Not Necessary	574.48 FL	*- FL
14	1		*REAR TAILGATE INNER TRIM	Cut	264.48 FL	*264.48 FL
15	1		*REAR BUMPER	Broken	1,380.72 FL	*985.00 FL
16	1		*REAR BUMPER REFLECTOR RH	Scratched	80.72 FL	*80.72 FL
17	1		*REAR BUMPER COVER RH	Scratched	95.72 FL	*32.00 FL
18	1		*REAR BUMPER SIDE RETAINER RH	Broken	48.20 FL	*48.20 FL
19	1		*REAR BUMPER SIDE RETAINER LH	Broken	48.20 FL	*48.20 FL
20	1		*REAR END PANEL	Buckled	721.80 FL	*721.80 FL
21	1		*REAR QUARTER GLASS SEAL LH	Cut	68.80 FL	*68.80 FL
22	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
24	1		*SET REAR PARKING SENSOR	Faulty	250.00 FS	*200.00 FS
25	1		*SUNDRIES (SAND PAPER,WELDING WIRE ETC)	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,300.09</b>	<b>5,947.73</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,578.02	1,135.55
<b>Total Parts (\$\$)</b>	<b>6,722.07</b>	<b>4,812.18</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS ADN COMPONENTS	New	800.00	600.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	New	100.00	30.00
3	TO REMOVE & REFIT REAR TAILGATE MECHANISM	New	100.00	60.00
4	TO REMOVE & REFIT REAR TAILGATE WINDSCREEN	New	150.00	80.00
5	TO REMOVE & REFIT REAR BUMPER REVERSE SENSORS	New	80.00	30.00
6	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	800.00	680.00
7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	50.00	40.00
8	TO VACUUM ,WAXING & CLEAN	New	50.00	20.00
9	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,180.00</b>	<b>1,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >