

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23002509/TVY3Q2**Date:** 02/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00041612201
Claimant Vehicle No :	SMQ5030L	Insured Vehicle No :	SKH5245E
Date of Loss:	18/01/2023	Nature of Claim: TP	Claim No: SNM23D201793/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ5030L		
Make & Model:	MERCEDES-BENZ A180, 1.6 FL STYLE (R17 HLG) (A)	Engine No:	27091031261403
Reg. Date:	19/06/2017 (Man. Year: 2017)	Chassis No:	WDD1760422J594726
Colour:	Yellow	Odometer:	131484 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,806.74	2,400.94	22,405.80	90.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,250.00	610.00	5,640.00	90.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,056.74	3,010.94	28,045.80	90.31
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	31,056.74	2,400.00	28,656.74	92.27

INSPECTION

Date of Assignment:	11/03/2023	
Date Inspected:	13/03/2023	Inspected At: 8 Kaki Bukit Ave 4 #01-53, Premier @ Kaki Bukit
Estimated Period of Repair:	2.0 days	Repairer: MCR AUTOWORKS (HQ)

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 May 2023)
Parts:	144	MERCEDES-BENZ A180 1.6 FL STYLE (R17 HLG) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ5030L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,431.33 FL	*1,431.33 FL
2	1		*REAR BUMPER LOWER BLACK TRIM	Deformed	273.90 FL	*273.90 FL
3	12		*RIVET	Necessary	57.72 FL	*57.72 FL
4	6		*SPACER RING	Necessary	38.10 FL	*38.10 FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	73.00 FL	*- FL
6	1		*CENTRE BASIC MOUNTING FOR REAR BUMPER	Not Necessary	115.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Not Necessary	641.00 FL	*- FL
8	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	164.00 FL	*- FL
9	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	164.00 FL	*- FL
10	1		*REAR TAILLAMP ASSEMBLY RH	Not Necessary	898.00 FL	*- FL
11	1		*REAR TAILLAMP ASSEMBLY LH	Not Necessary	898.00 FL	*- FL
12	1		*REAR TAILLAMP HOLDER RH	Not Necessary	198.00 FL	*- FL
13	1		*REAR TAILLAMP HOLDER LH	Not Necessary	198.00 FL	*- FL
14	1		*REAR TAILGATE	Not Necessary	2,495.00 FL	*- FL
15	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	384.00 FL	*- FL
16	1		*REAR TAILGATE TOP LOCK	Not Necessary	485.00 FL	*- FL
17	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	412.00 FL	*- FL
18	1		*REAR TAILGATE EMBLEM	Not Necessary	85.00 FL	*- FL
19	1		*REAR TAILGATE A180 EMBLEM	Not Necessary	75.00 FL	*- FL
20	1		*REAR END PANEL	Not Necessary	965.00 FL	*- FL
21	1		*REAR END PANEL TOP GARNISH	Not Necessary	450.00 FL	*- FL
22	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	543.00 FL	*- FL
23	1		*REAR FENDER LH	Not Necessary	1,524.68 FL	*- FL
24	1		*REAR DOOR LH	Not Necessary	1,923.33 FL	*- FL
25	1		*REAR EXHAUST PIPE	Not Necessary	1,356.00 FL	*- FL
26	2		*REAR EXHAUST MOUNTING	Not Necessary	116.00 FL	*- FL
27	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	476.00 FL	*- FL
28	1		*REAR SHOCK ABSORBER LH	Not Necessary	711.72 FL	*- FL
29	1		*REAR KNUCKLE ARM LH	Not Necessary	910.25 FL	*- FL
30	1		*REAR LOWER ARM RH	Not Necessary	532.12 FL	*- FL
31	1		*REAR WHEEL BEARING LH	Not Necessary	165.24 FL	*- FL
32	6		*REVERSE SENSOR	Not Necessary	1,094.88 FL	*- FL
33	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	431.00 FL	*- FL
34	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
35	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
36	1		*SET REAR TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*REAR TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
39	1		*REAR END PANEL SEALANT	Not Necessary	150.00 FS	*- FS
40	1		*REAR FENDER LH SEALANT	Not Necessary	150.00 FS	*- FS
41	1		*REAR DOOR LH SEALANT	Not Necessary	150.00 FS	*- FS
42	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Not Necessary	150.00 FS	*- FS
43	1		*SET REAR BUMPER CANARDS	Not Necessary	600.00 FS	*- FS
44	1		*REAR BUMPER LOWER DIFFUSER -AFTERMARKET	Deformed	850.00 FS	*750.00 FS
45	1		*ROCKER PANEL GARNISH LH -AFTERMARKET	Not Necessary	650.00 FS	*- FS
46	1		*REAR WHEEL RIM LH	Not Necessary	2,500.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR TYRE LH	Not Necessary	500.00 FS	*- FS
48	1		*REAR TAILGATE REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					26,835.27	2,581.05
- List Item Discount on L Items 10.00/10.00% (\$\$)					2,028.53	180.11
Total Parts (\$\$)					24,806.74	2,400.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE & REFIX PARTS	New	1,800.00	250.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,800.00	300.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS	New	150.00	0.00
5	TO TRANSFER REAR TAILGATE MECHANISM	New	150.00	0.00
6	TO TRANSFER REAR DOOR MECHANISM LH	New	150.00	0.00
7	TO REMOVE & REFIX REAR TAILGATE REVERSE CAMERA	New	150.00	0.00
8	TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	120.00	30.00
9	TO REMOVE & REFIX REAR EXHAUST PIPE	New	150.00	0.00
10	TO REMOVE & REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
11	TO REMOVE & REFIX REAR UNDERCARRIAGE	New	500.00	0.00
12	TO REMOVE & REFIX REAR TYRE AND CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
13	TO CONDUCT FOUR WHEEL ALIGNMENT	New	150.00	0.00
14	TO APPLY ANTI RUST ON AFFECTED PARTS	New	150.00	0.00
15	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
16	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT ,PROGRAMMING & CALIBRATION	New	480.00	0.00
Gross Labour Cost (S\$)			6,250.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >