

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23002515/RQY3Q2**Date:** 18/05/2023**REFERENCE**

Insured/Claimant:	RITESH AJMANI	Policy No:	SP2001628836	
Date of Loss:	03/03/2023	Nature of Claim:	OD	Claim No: 202332005950

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ9286S		
Make & Model:	SKODA KODIAQ, 1.4 TSI AMBITION PLUS (A)	Engine No:	CZD771795
Reg. Date:	25/05/2021 (Man. Year: 2021)	Chassis No:	TMBKC7NS2M8049808
Colour:	Blue	Odometer:	34713 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$173,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,056.39	5,130.09	3,926.30	43.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,060.00	3,520.00	1,540.00	30.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,116.39	8,650.09	5,466.30	38.72
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	13,516.39	8,050.09	5,466.30	40.44
+ GST 8.00/8.00% (\$\$)	1,081.31	644.01	437.30	40.44
Nett Amount (\$\$)	14,597.70	8,694.10	5,903.60	40.44

INSPECTION

Date of Assignment:	09/03/2023	
Date Inspected:	10/03/2023	Inspected At: Volkswagen Group Singapore Pte Ltd 247 ALEXANDRA ROAD Singapore 159934
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2023)
Parts:	144	SKODA KODIAQ 1.4 TSI AMBITION PLUS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ9286S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR FRT BUMPER	Deformed	1,987.76 FS	*1,987.76 FS
2	1		*SENSOR BRACKET	Necessary	13.73 FS	*13.73 FS
3	1		*SENSOR BRACKET	Necessary	21.24 FS	*21.24 FS
4	1		*2K-PLASTIC ADHESIVE	Necessary	76.18 FS	*76.18 FS
5	1		*BONDING AGENT FOR PLASTIC	Necessary	66.93 FS	*66.93 FS
6	1		*GUIDE PIEC BUMPER SIDE BRACKET RH	Not Necessary	61.54 FS	*- FS
7	1		*FRONT SPOI	Scratched	396.92 FS	*396.92 FS
8	1		*END PLATE BUMPER SPOILER CLOSING ELEMENT	Not Necessary	166.82 FS	*- FS
9	1		*TRIM TOWING COVER	Cut	17.42 FS	*17.42 FS
10	1		*GRILLE RADIATOR GRILLE	Not Necessary	382.28 FS	*- FS
11	1		*COVER STRI RADIATOR GRILLE CHROM	Not Necessary	425.40 FS	*- FS
12	1		*UNBEKANNT BUMPER CTR LOWER GRILLE	Cracked	175.62 FS	*175.62 FS
13	1		*CAP BUMPER LOWER GRILLE RH	Deformed	53.09 FS	*53.09 FS
14	1		*TRIM FOR B RHS LOWER GRILLE (SENSOR GRILLE)	Not Necessary	25.87 FS	*- FS
15	1		*AIR DUCT AIR GUIDE LOWER	Cracked	97.88 FS	*97.88 FS
16	1		*REINFORCEM	Bent	876.29 FS	*876.29 FS
17	1		*CROSS MEMB	Not Necessary	92.60 FS	*- FS
18	2		*HEX SOCKET HEAD BOLT	Not Necessary	4.27 FS	*- FS
19	1		*UNBEKANNT RHS H/LAMP	Not Necessary	2,767.52 FS	*- FS
20	1		*TRIM FOR W RHS WHEEL ARCH	Cracked	248.90 FS	*248.90 FS
21	1		*FOIL INSCR RHS FENDER NAME PLATE (L&K)	Necessary	77.57 FS	*77.57 FS
22	1		*RHF FENDER	Bent	963.13 FS	*963.13 FS
23	1		*RHS FENDER BRACKET	Necessary	57.43 FS	*57.43 FS
Total Parts (S\$)					9,056.39	5,130.09

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	TO ALIGN LED HEADLIGHT	New	100.00	0.00
4	LABOUR	New	2,160.00	720.00
5	SPRAY PAINT	New	2,040.00	2,040.00
Gross Labour Cost (S\$)			5,060.00	3,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >