

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23002517/RWY3Q2**Date:** 25/04/2023**REFERENCE**

Insured/Claimant: MERCEDES-BENZ SINGAPORE PTE LTD(MBS)

Policy No: SP2003915046

Date of Loss: 11/01/2023

Nature of Claim: OD

Claim No: 202332004476

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNH6534D**

Make & Model: MERCEDES-BENZ E300, 2.0 (A)

Engine No: 27492032012379

Reg. Date: 17/11/2022 (Man. Year: 2022)

Chassis No: W1K2130532B040744

Colour: Black

Odometer: 5254 km

Engine Capacity: 1991 cc

Market Value/New Car Price: S\$302,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35 R19

Rear Tyre Size: 275/35 R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,160.34	987.75	172.59	14.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	2,260.00	640.00	22.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,060.34	3,247.75	812.59	20.01
- Excess (S\$)	700.00	700.00	0.00	0.00
(S\$)	3,360.34	2,547.75	812.59	24.18
+ GST 8.00/8.00% (S\$)	268.83	203.82	65.01	24.18
Nett Amount (S\$)	3,629.17	2,751.57	877.60	24.18

INSPECTION

Date of Assignment: 09/03/2023

Date Inspected: 09/03/2023 Inspected At:

Cycle & Carriage Industries Pte Ltd (Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2023)
Parts:	M1-COUPE	MERCEDES-BENZ E300 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNH6534D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	987.75 FS	*987.75 FS
2	1		*RIGHT REAR BUMPER LATERAL SUPPORT	Not Necessary	89.31 FS	*- FS
3	1		*RIGHT REAR BASIC CARRIER,BUMPER	Not Necessary	83.28 FS	*- FS
Total Parts (S\$)						1,160.34 987.75

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING TO REPAIR AFFECTED AREAS,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	1,200.00	960.00
2	RESPRAY REAR BUMPER	New	1,200.00	800.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS ,RESET SYSTEM TO STANDARD SETTINGS	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
Gross Labour Cost (S\$)			2,900.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >