

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG123002520/ANY3Q2**Date:** 19/06/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SJH3922J **Insured Vehicle No :** GBF8969Y

Date of Loss: 06/03/2023 Nature of Claim: TP Claim No: CDMCG23000552

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH3922J**

Make & Model: MERCEDES-BENZ GLC300, 2.0 COUPE (A) Engine No: 26492080255249

Reg. Date: 26/08/2022 (Man. Year: 2022) Chassis No: W1N2533842G106927

Colour: Black Odometer: 19398 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50 R19 Rear Tyre Size: 255/50 R19

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,756.50	11,856.45	7,900.05	39.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,500.00	1,920.00	3,580.00	65.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,256.50	13,776.45	11,480.05	45.45
Approved Total (Overridden) (S\$)		11,000.00		
Nett Amount (S\$)	25,256.50	11,000.00	14,256.50	56.45

INSPECTION

Date of Assignment: 07/03/2023

Date Inspected: 07/03/2023 Inspected At: 25 KAKI BUKIT ROAD 4
#06-38 SYNERGY @ KB
SINGAPORE 417800
Repairer: Jd Motorsports Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Jun 2023)	
Parts:	N/A	MERCEDES-BENZ GLC300 2.0 COUPE (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH3922J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	3,850.00 F	*3,850.00 FL
2	2		*REAR TAIL GATE ABSORBER	Not Necessary	570.00 F	*- FL
3	1		*REAR BUMPER	Deformed	1,850.00 F	*1,350.00 FL
4	1		*REAR BUMPER GRILLE	Deformed	1,400.00 F	*539.00 FL
5	1		*REAR BUMPER GRILLE UPPER CHROME (CENTINTRE)	Cracked	230.00 F	*230.00 FL
6	1		*REAR BUMPER LOWER GRILLE	Not Necessary	290.00 F	*- FL
7	1		*REAR BUMPER GRILLE LOWER CHROME (R)	Not Necessary	180.00 F	*- FL
8	1		*REAR BUMPER LOWER GARNISH (CENTRA)	Not Necessary	273.00 F	*- FL
9	1		*REAR BUMPER LOWER GARNISH (L)	Not Necessary	350.00 F	*- FL
10	1		*REAR BUMPER LOWER GARNISH (R)	Not Necessary	350.00 F	*- FL
11	1		*REAR NUMBER PLATE GARNISH	Not Necessary	130.00 F	*- FL
12	2		*TAIL GATE KICK SENSOR	Not Necessary	416.00 F	*- FL
13	1		*TAIL GATE KICK SENSOR MODULE	Cracked	550.00 F	*485.00 FL
14	1		*REAR BUMPER REFLECTOR (R)	Not Necessary	180.00 F	*- FL
15	4		*REAR PARKING SENSOR	Damaged (3 PCS ONLY)	1,036.00 F	*777.00 FL
16	1		*REAR BUMPER INNER GARNISH	Deformed	430.00 F	*210.00 FL
17	1		*REAR BUMPER INNER SPONGE	Cracked	220.00 F	*220.00 FL
18	1		*REAR TAIL LAMP (L)	Cracked	850.00 F	*850.00 FL
19	1		*REAR TAIL LAMP LOWER BUCKET(L)	Cracked	280.00 F	*75.00 FL
20	1		*REAR TAIL GATE LAMP (R)	Cracked	600.00 F	*560.00 FL
21	1		*REAR TAIL GATE LAMP UPPER CHROME (R)	Not Necessary	140.00 F	*- FL
22	1		*REAR TAIL GATE LAMP (L)	Cracked	600.00 F	*560.00 FL
23	1		*REAR TAIL GATE LAMP UPPER CHROME (L)	Not Necessary	140.00 F	*- FL
24	1		*REAR TAIL GATE HANDLE SWITCH	Cracked	380.00 F	*380.00 FL
25	1		*REAR TAIL GATE HANDLE SWITCH EMBLEM	Damaged	230.00 F	*230.00 FL
26	1		*REAR TAIL GATE LOCK	Damaged	480.00 F	*480.00 FL
27	1		*REAR WHEEL ARCH GARNISH	N/S Cracked	429.00 F	*214.50 FL
28	2		*REAR SIDE RETAINER	Necessary	325.00 F	*210.00 FL
29	1		*REAR REINFORCEMENT	Dented	950.00 F	*895.00 FL
30	1		*REAR TAIL GATE INNER TRIM BOARD	Cracked	650.00 F	*650.00 FL
31	1		*REAR TAIL GATE INNER TRIM BOARD CLIP (11 PCS)	Necessary	93.50 F	*30.00 FL
32	4		*REAR END PANEL TOP GARNISH CLIP	Not Necessary	48.00 F	*- FL
33	1		*REAR END PANEL (OUTER)	Repair	385.00 F	*- FL
34	2		*REAR LOWER HEAT SHIELD	Not Necessary	330.00 F	*- FL
35	1		*EMBLEM GLC300	Necessary	150.00 F	*95.00 FL
36	1		*EMBLEM 4MATIC	Necessary	180.00 F	*90.00 FL
37	1		*REAR NUMBER PLATE	Cracked	45.00 FS	*30.00 FS
38	1		*REAR NUMBER PLATE HOLDER	Cracked	30.00 FS	*30.00 FS
39	1		*RIVET (6 PCS)	Necessary	72.00 FS	*50.00 FS
40	4		*SILICON	Necessary	64.00 FS	*64.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 19,756.50 13,154.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 0.00/10.00% (\$)					0.00	1,298.05
Total Parts (\$)					19,756.50	11,856.45
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR & PARTS TO REPLACE ABOVE MENTIONED PARTS	New	1,800.00	700.00
2	LABOUR & PAINT TO SPRAY ACCIDENT AFFECTED AREA	New	1,800.00	750.00
3	LABOUR TO RE-WIRE ELECTRICAL PARTS	New	200.00	30.00
4	LABOUR TO SPRAY ANTI-RUSH	New	300.00	60.00
5	LABOUR TO UPHOSTLER FOR REPAIR WORK	New	350.00	60.00
6	LABOUR TO REMOVE AND REFIT REAR WINDSCREEN	New	450.00	120.00
7	LABOUR TO REPROGRAMMING AND CODING ELECTRICAL PARTS	New	600.00	200.00
Gross Labour Cost (S\$)			5,500.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >