

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23002521/RQCE2**Date:** 02/08/2023**REFERENCE**

Insured/Claimant:	GLYN CARROLL	Policy No:	7210000351	
Date of Loss:	03/03/2023	Nature of Claim:	OD	Claim No: 1397721186SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK2967Y		
Make & Model:	AUDI Q3, 1.4 TFSI S TRONIC (17") (A)	Engine No:	CZDC23836
Reg. Date:	14/01/2021 (Man. Year: 2020)	Chassis No:	WAUZZZF34M1064798
Colour:	Blue	Odometer:	24260 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$153,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,553.00	6,995.36	5,557.64	44.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,752.00	4,942.00	7,810.00	61.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,305.00	11,937.36	13,367.64	52.83
+ GST 8.00/8.00% (S\$)	2,024.40	954.99	1,069.41	52.83
Nett Amount (S\$)	27,329.40	12,892.35	14,437.05	52.83

INSPECTION

Date of Assignment:	10/03/2023	
Date Inspected:	08/03/2023	Inspected At: 281 Alexandra Road Singapore 159938 Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Bent	3,192.00 FS	*2,553.60 FS
2	1		*FRONT DOOR OUTER SEAL - LH	Necessary	196.00 FS	*156.40 FS
3	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	173.00 FS	*- FS
4	1		*FRONT DOOR CATCH	Not Necessary	141.00 FS	*- FS
5	1		*FRONT DOOR COVER - LH	Scratched	299.00 FS	*239.20 FS
6	1		*FRONT WINDOW REGULATOR - LH	Not Necessary	321.00 FS	*- FS
7	1		*REAR DOOR - LH	Bent	3,313.00 FS	*2,650.40 FS
8	1		*REAR DOOR OUTER SEAL - LH	Necessary	159.00 FS	*127.20 FS
9	1		*REAR DOOR CATCH	Bent	141.00 FS	*112.80 FS
10	1		*REAR SILL PANEL SEAL - LH	Not Necessary	159.00 FS	*- FS
11	1		*REAR DOOR HINGE HALF UPPER PART - LH LOWER	Not Necessary	54.00 FS	*- FS
12	1		*REAR DOOR HINGE HALF UPPER PART - LH UPPER	Not Necessary	51.00 FS	*- FS
13	1		*REAR DOOR HINGE HALVES - LH UPPER	Not Necessary	56.00 FS	*- FS
14	1		*REAR DOOR HINGE HALF LOWER PART - LH LOWER	Not Necessary	57.00 FS	*- FS
15	1		*REAR DOOR COVER - LH	Scratched	286.00 FS	*228.80 FS
16	1		*REAR BUMPER	Repair	1,839.00 FS	*- FS
17	1		*REAR BUMPER FIXING PARTS	Not Necessary	230.00 FS	*- FS
18	1		*REAR BUMPER SPOILER	Scratched	540.00 FS	*431.60 FS
19	1		*REAR BUMPER REFLECTOR - LH	Not Necessary	49.00 FS	*- FS
20	2		*REAR WHEEL COVER - LH / RH	N/S Missing/O/S Necessary	598.00 FS	*478.40 FS
21	1		*FRONT WHEEL COVER - LH	Not Necessary	299.00 FS	*- FS
22	1		*SUNDRIES	Necessary	400.00 FS	*16.96 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 12,553.00 6,995.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	800.00
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER, LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS FRONT FENDER AND LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	1,500.00
4	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, HINGES, LHS REAR FENDER AND REAR BUMPER	New	5,000.00	1,650.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REPAIR LHS B-PILLAR (Supplementary)	New	800.00	250.00
7	TO RESPRAY LHS B-PILLAR (Supplementary)	New	1,600.00	550.00
Gross Labour Cost (\$)			12,752.00	4,942.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >