

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 17 Apr 2023

Preliminary Advice

Vehicle No	: SMS3706Z	Accident Date	: 25/02/2023
Make	: HONDA FIT	Policy No.	: SP2003972742
Assignment Date	: 09/03/2023	Excess	: S\$2,000.00
Date of Inspection	: 10/03/2023	Est. Duration of Repair	: 28
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	70,236.00
Revised Amount	:S\$	55,406.00
Check Items (Estimated)	:S\$	11,996.00
Total	:S\$	67,402.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	25,673.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,327.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE REPAIRER WILLING TO UNDERTAKE THE REPAIR COST AT \$50,000.00 ON LUMP SUM BASIS.
Vehicle is repairable provided the repairs are carried out using proper tools and equipments, in accordance to manufacturer guidelines. We suggest to send vehicle for chassis alignment test at STA after the completion of repair.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.