

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## **OPINION ON REPAIR COST FOR VEHICLE NO. SNB 5320S**

Qty	Description of Parts	Condition	Recommended (\$)
	LABOUR		
	TO REPAIR THE DENT ON FRONT RIGHT DOOR.		140.00
	TO RESPRAY FRONT RIGHT DOOR.		220.00
			360.00
	GRAND TOTAL		360.00

RECOMMENDED COST OF REPAIRS	360.00
-----------------------------	--------

Report Ref No. CS/SPF23002529/Svy3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$360-\$400

//

S MOHAMED IRFAN BIN MOHAMED IQUBAL

**Asst. Automotive Assessor** 

X:2.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

**Licensed Appraiser**