



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23002529/Svy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	19/07/2023
HEMMANT ROADSINGAPORE 438675			
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 508A	Veh. Inspected	SNB 5320S
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/015	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	09/03/2023
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI CN7 AVANTE 1.6	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	KMHLN41ETNU214445	Colour	BLUE
Odometer	12479 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55R16	HANKOOK	6 mm
L/H Front Tyre	205/55R16	HANKOOK	6 mm
R/H Rear Tyre	205/55R16	HANKOOK	6 mm
L/H Rear Tyre	205/55R16	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/02/2023	Inspection Date	10/03/2023
Survey held at	10 BUANGKOK VIEW, SINGAPORE 539747		
Repairer	KOMOCO MOTORS PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	