

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988**Our File No:** CS/EG123002536/AVY3E2**Date:** 13/04/2023**REFERENCE**

Insured/Claimant:	KAMSANI BIN KAMSUN	Policy No:	DMPG22010892	
Date of Loss:	24/02/2023	Nature of Claim:	OD	Claim No: CDMPG23000464

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG4449J	Engine No:	B095I629N46B20BZ
Make & Model:	BMW 318I, 2.0 (A)	Chassis No:	WBAPF72010A793609
Reg. Date:	31/08/2010 (Man. Year: 2010)	Odometer:	254373 km
Colour:	Black		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	S\$76,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,653.25	16,342.61	9,310.64	36.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	2,520.00	1,520.00	37.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,693.25	18,862.61	10,830.64	36.48
Approved Total (Overridden) (S\$)		15,000.00		
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
Nett Amount (S\$)	28,693.25	14,000.00	14,693.25	51.21

INSPECTION

Date of Assignment: 09/03/2023

Date Inspected: 10/03/2023 Inspected At:

YK Supreme Autowerkz Pte Ltd (HQ)
Blk 3012 Bedok Industrial Park E #01-2016
Singapore 489978

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2023)
Parts:	143	BMW 318I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG4449J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	2,422.25 F	*1,180.00 FL
2	1		*FRONT BUMPER CARRIER	Not Necessary	574.00 F	*- FL
3	1		*FRONT BUMPER FOG LAMP	Not Necessary	289.45 F	*- FL
4	2		*FRONT GRILLE	Not Necessary	273.20 F	*- FL
5	1		*HEADLIGHT	Broken	1,274.35 F	*1,274.35 FL
6	1		*BONNET	Repair	1,289.60 F	*- FL
7	1		*FRONT WINDSCREEN	Cracked	1,020.85 F	*1,020.85 FL
8	1		*FRONT WINDSCREEN TOP MOULDING	Necessary	78.60 F	*78.60 FL
9	1		*FRONT WINDSCREEN RAIN SENSOR	Not Necessary	799.80 F	*- FL
10	2		*FRONT WINDSCREEN SEALANT	Necessary	265.20 F	*265.20 FL
11	1		*FRONT FENDER	Dented	742.30 F	*742.30 FL
12	1		*FRONT FENDER SHROUD	Torn	157.25 F	*157.25 FL
13	1		*FRONT DOOR PANEL RH	Dented	1,271.50 F	*1,271.50 FL
14	1		*FRONT DOOR SIDE VIEW MIRROR	Repair	924.30 F	*- FL
15	1		*FRONT ALLOY RIM	Cut	1,131.45 F	*1,131.45 FL
16	1		*FRONT WHEEL BEARING	Damaged	483.65 F	*483.65 FL
17	1		*FRONT SPRING STRUT	Not Necessary	514.20 F	*- FL
18	1		*FRONT GUIDE SUPPORT	Not Necessary	126.50 F	*- FL
19	1		*FRONT TIE ROD	Bent	296.30 F	*296.30 FL
20	1		*HYDRO STEERING GEAR	Not Necessary	2,275.10 F	*- FL
21	1		*FRONT KNUCKLE ARM	Damaged	466.30 F	*466.30 FL
22	1		*FRONT LOWER ARM	Bent	257.10 F	*257.10 FL
23	1		*FRONT WISHBONE	Bent	254.55 F	*254.55 FL
24	1		*DASHBOARD ASSEMBLY	Broken	3,778.15 F	*3,778.15 FL
25	1		*AIR BAG MODULE RH	Activated	1,397.55 F	*1,397.55 FL
26	1		*STEERING WHEEL	Broken	1,138.00 F	*1,138.00 FL
27	1		*FRONT PASSENGER AIR BAG	Activated	1,291.75 F	*1,291.75 FL
28	1		*FRONT TYRE (50%)	Cut	300.00 FS	*150.00 FS
29	1		*SEAT BELT BUCKLE RIGHT FRONT	Activated	360.00 F	*360.00 FL
30	1		*BATTERY TERMINAL WITH FUSE & WIRE	Activated	200.00 F	*200.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,653.25	17,194.85
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	852.24
Total Parts (\$\$)	25,653.25	16,342.61

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACED DAMAGED PARTS	New	1,440.00	1,000.00
2	TO RESPRAY REPLACED AND AFFECTED PANELS	New	1,300.00	800.00
3	TO CARRY OUT ANTI RUST TREATMENT	New	160.00	40.00
4	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	160.00	120.00
5	TO CHECK WIRING FOR PROPER FUNCTION	New	80.00	30.00
6	TO REMOVE AND REPLACE DASHBOARD ASSEMBLY	New	350.00	180.00
7	TO REMOVE AND REPLACE AIR BAG AND NECESSARY PARTS	New	300.00	200.00
8	CARRY OUT DIAGNOSTIC AND RESET TO SPECIFICATION	New	250.00	150.00
Gross Labour Cost (S\$)			4,040.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >