

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	UNITED OVERSEA	AS INSURANCE LTD		Ref:	CS/UOI23002542/Any3m4
	146 ROBINSON RO #02-01 UOI BUILDI	DAD NGSINGAPORE 068909		Date:	19/06/2023
				Code:	UOI2
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBL 6301E	Veh. Inspected	l	GBH 9806S
	Policy No.		Coverage (\$)		0.00
	Claim No.	M12D00122303	Excess (\$)		0.00
	Assign From	JOANNE YONG	Assign Date		09/03/2023
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE	c.c		2982
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	KDH2010230995	Colour		WHITE
	Odometer	112241 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195R15C	BRIDGESTONE		6 mm
	L/H Front Tyre	195R15C	BRIDGESTONE		6 mm
	R/H Rear Tyre	195R15C	BRIDGESTONE		6 mm
	L/H Rear Tyre	195R15C	BRIDGESTONE		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	06/03/2023	Inspection Dat	е	15/03/2023
	Survey held at	MG SOLUTION PTE LTD	-		
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	STIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				